


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12788	Main Street: NASSAU_BV	Cross Street: SPRAGUE_AV	Location: SE
ADA ID: FD8D8D6A9861	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	91.5	N/A	Grade Break?	N/A		
			Yes	Ramp Width (in)	53.0	N/A	Grade Break Slope (%)	0.0		
			No	Ramp Slope (%)	17.5	N/A	Grade Break XSlope (%)	0.0		
			Yes	Ramp XSlope (%)	2.5					
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
Surveyor Notes:										
N/A										
PROW/ADA:										
R304.2.2										

