## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5799 Main Street: ROCKWELL_CHURCH_RD			Cross Street: W_SUGAR_CREEK_RD				Location:	NE		
ADA ID: FDCC6CEA1312 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	FRANK INNESS	Possible Solutions:	Compliance Description			Data	Data Compliance Description		Data	
1 March 1 1	WELL A DEAL	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	59.0	Yes	Ramp Slope (%)	6.9	
1 person	and the second			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.3	
11 Calibra	Row Maria			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
1 1 the star	(B)			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
1 13	1- A DESCRIPTION			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Charles	4		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	ALLE STATE	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A CARLER CARLES		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	1 million and the second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	1 Million	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Carlo I PILL	(111:1	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1116 C 3			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name ROCKWELL CHURCH RD					X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

