


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10017628	Main Street: TIMBER_RIDGE_RD	Cross Street: N/A	Location: W
ADA ID: FDE0F2E10E68	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Yes	Ramp Length (in)	49.5
			Yes	Ramp Width (in)	54.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	3.7
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	48.0
			Yes	Landing Width (in)	55.0
			No	Landing Slope (%)	2.5
			No	Landing X Slope (%)	5.5
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	5.1
			N/A	Flare Traversable RT?	No
			No	DWS Provided?	No
			N/A	DWS Contrast?	No
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	No
			N/A	DWS Offset (in)	N/A
			Yes	Shared Landing?	Yes
			Yes	Gutter Ponding?	No
<p>Total Cost:</p> <p>\$ 1850.00</p>			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To E
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	5.9
				X Walk 1 X Slope (%)	5.1
			N/A	Ramp inside XWalk1?	N/A
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		
			N/A		
			N/A	Clear Space?	Yes
			N/A	Clear Space to XWalk (in)	N/A
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

