

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10663Main Street: FINCHLEY_DRCross Street: MIRAMAR_DRLocation:SWADA ID: FE533CC8273FRamp Type: Combination1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score:22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
StopSign
Stop Condition-Street 1
MIRAMAR DR
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

LT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.3, R304.3.2

N/A N/A

Total Cost: \$ 1800.00 N/A

Compliance Description Data Compliance Description Data Ramp Length LT (in) N/A N/A 68.5 Ramp Length RT (in) 58.0 Yes Ramp Width LT (in) 60.0 Yes Ramp Width RT (in) 60.5 Yes No Ramp Slope LT (%) 1.1 Ramp Slope RT (%) 11.7 Ramp XSlope LT (%) Yes Ramp XSlope RT (%) Yes 1.1 1.5 N/A Ramp Length (in) 36.0 Yes Ramp Slope (%) 0.6 47.5 No Ramp XSlope (%) 2.5 No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A N/A Landing Width (in) **DWS Contrast?** N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk2? N/A Painted X Walk1? No N/A To SE X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 4.7 N/A X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.4 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A

N/A

N/A

Yes

Any Obstruction?

Obstruction Type

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

N/A

N/A

Good 17.6





