

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50608	Main Street: DENBUR_DR			Cross	Street:	DOWNY_BIRCH_RD	Location:	SW			
ADA ID: FE7E3E27AE02	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Compliance:				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data	Data Compliance Description			
		Remove & Replace Entire I	Ramp		N/A	Ramp Length LT (in)	68.5	N/A	Ramp Length RT (in)	72.0	
			•		Yes	Ramp Width LT (in)	60.5	N/A	Ramp Width RT (in)	59.5	
	No.				Yes	Ramp Slope LT (%)	5.5	N/A	Ramp Slope RT (%)	1.6	
8					Yes	Ramp XSlope LT (%)	0.4	N/A	Ramp XSlope RT (%)	0.7	
	Hard and				N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.8	
the second second	a an indiana				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.2	
DENEUR DE	<u>⊾</u>	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the second second	-	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
e.					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
The second second					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	A MARTINE -				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	SAL ST	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
New States States	The State May	Not Found, R304.2.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	Contraction of the				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
State of the second state of the					N/A	Shared Landing?	N/A				
1. Kar B. B. Carth	WC				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None	-			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	DENBUR DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	N/A	
		Total Cost: \$	5 1	600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			-					N/A	Any Obstruction?	N/A	
						the local			Obstruction Type		

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 8.7





