

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 21114 Main Street: BENT BRANCH RD Cross Street: CARMEL\_RD Location: NE **Overall Compliance: No** Severity Score: 13.75 **ADA ID: FEAA1F7F4339** Ramp Type: Directional1 Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 



**BENT BRANCH RD** Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Cumping Nation					
Surveyor Notes:					
N/A					
PROW/ADA:					
R304.2.2					

1600.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance Description	Dat	
N/A	Ramp Length (in)	79.0	N/A	Grade Break?	N/A	
Yes	Ramp Width (in)	51.0	N/A	Grade Break Slope (%)	0.	
No	Ramp Slope (%)	11.9	N/A	Grade Break XSlope (%)	0.	
Yes	Ramp XSlope (%)	4.0				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No		Road Slope (%)	0.	
	X Walk 1 Direction	To SW		Road X Slope (%)	9.	
	X Walk 1 Width (in)	N/A		Clear Space?	N/A	
	X Walk 1 Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	9.5	N/A	Storm Grate/Utility Hazard?	N/A	
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Goo	
		N/A	N/A	Curb Slope (%)	13.	





Total Cost:

