cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16237	6237 Main Street: ELLENWOOD_PL			treet:	FREELAND_LN	Location:	Ν		
ADA ID: FED39BD28993	28993 Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description D			Data Compliance Description		Data
and the states i		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	82.0	No	Ramp Slope (%)	8.7
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.5
The last calls		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
1 July and the second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	E Som			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Track .				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E Contraction of the contraction		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5 /	Bar inde	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
FREE	er alle			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ND	LN			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
S. S				N/A	Shared Landing?	N/A			
	AND A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the second second	Partie and	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FREELAND LN	-			X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	3.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	3.2
Street 2 Name	ELLENWOOD PL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.3	N/A	Clear Space?	N/A
					Road X Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
		· · ·				N/A			N/A

s Surface Condition? (G/P)

Good

