



# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 5924	Main Street: GUM_BRANCH_RD	Cross Street: WOODLYNN_DR	Location: NE
ADA ID: FEDBB375D2C7	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	31.0
			Yes	Ramp Width LT (in)	68.0
			Yes	Ramp Slope LT (%)	4.1
			No	Ramp XSlope LT (%)	2.9
			N/A	Ramp Length (in)	31.0
			Yes	Ramp Width (in)	48.0
	Surveyor Notes:		N/A	Flare Type LT	N/A
	RP & LT RP < 5%		N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
<p>PROW/ADA:</p> <p><b>R304.5.3, R304.3.2</b></p>			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To W
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.8
				X Walk 1 X Slope (%)	3.9
	Total Cost:	\$ 1800.00	N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
				Clear Space?	N/A
				Clear Space to XWalk (in)	N/A
				Any Obstruction?	N/A
				Obstruction Type	N/A
				Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
					N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	2.4