


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 14495	Main Street: EASTWAY_DR	Cross Street: PINECREST_AV	Location: NW
ADA ID: FEEE0EDD4CB4	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	58.0
			Yes	Ramp Width LT (in)	73.0
			No	Ramp Slope LT (%)	14.1
			No	Ramp XSlope LT (%)	2.9
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
<p>Surveyor Notes:</p> <p>RT RP < 5%, NO LT SW</p> <p>PROW/ADA:</p> <p>R304.3.2, R304.5.3</p>			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To S
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	3.1
				X Walk 1 X Slope (%)	3.7
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
<p>Total Cost:</p> <p>\$ 1600.00</p>			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		
<p>Street 1 Name</p> <p>PINECREST AV</p> <p>Stop Condition-Street 1</p> <p>StopSign</p> <p>Street 2 Name</p> <p>N/A</p> <p>Stop Condition-Street 2</p> <p>N/A</p>			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
			N/A		
<p>Street 1 Name</p> <p>PINECREST AV</p> <p>Stop Condition-Street 1</p> <p>StopSign</p> <p>Street 2 Name</p> <p>N/A</p> <p>Stop Condition-Street 2</p> <p>N/A</p>			N/A	Surface Condition? (G/P)	Good
				Curb Slope (%)	11.9

