cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 24114	Main Street: ARBOR_POINTE_DR			Cross	Street:	STONEY_CORNER_LI	Location:	SE		
ADA ID: FF292EEC3B99	9 Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description				liance Description	Data	
	ALAR	Remove & Replace Curb I	Zamr	With	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	8.6
A CONTRACTOR OF THE OWNER OWNER OF THE OWNER OWNE OWNER OWNE		Two New Directional Ram	•	•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.5
	- 2 - 4	Equivalent.	pe e.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A CONTRACTOR	S. Strate				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
AREOR POINTE DR		6. 1	vor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	LA				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Att - 3				N/A	Shared Landing?	N/A			N/A
	F & Falle	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		4 5 3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1	Not Found, R304.2.2, R304	4.5.3		N/A	Painted X Walk1?	No		Painted X Walk2?	N/A No
	A star				N/A	X Walk 1 Direction	To N	N/A	X Walk 2 Direction	To NW
	HA MAR				N/A			N/A		N/A
		3			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	
	POINTE DR					X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	2.5
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	0.6
Street 2 Name STONEY C					N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign					Road Slope (%)	3.0	N/A	Clear Space?	N/A
						Road X Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A