


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10026423	Main Street: FARMBROOK_DR	Cross Street: N/A	Location: E
ADA ID: FF3CDD42EE6A	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 15.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length LT (in)	23.5
			Yes	Ramp Width LT (in)	48.0
			Yes	Ramp Slope LT (%)	5.4
			No	Ramp XSlope LT (%)	2.6
			Yes	Landing Length (in)	48.0
			No	Landing Width (in)	41.5
			Yes	Landing Slope (%)	1.6
			No	Landing X Slope (%)	3.7
			N/A	Landing Curb? (Y/N)	No
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.2.1, R305, R304.5.4</p>			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NW
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	1.2
				X Walk 1 X Slope (%)	2.0
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	1.9
				Road X Slope (%)	2.4
			Yes	Any Obstructions?	No
				Obstruction Type	
Total Cost:		\$ 3950.00			

