

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22758	Main Str	reet: RIDGE_OAK_DR	Cross Street: MOSS_RD				Location: E		
ADA ID: FF447DE954B3	Ramp Type: Perp		Initial Pass/Fail: Fail Over		Overall Complia	nce: N	o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
E And		Possible Solutions:	Compliance Description Data			Compliance Description Data			
	Alen:	Remove & Replace Entire Ramp.	N/A	Ramp Length (ir	ו) 92.0	No	Ramp Slope (%)	8.7	
A A A A A A A A A A A A A A A A A A A	A CONTRACT		No	Ramp Width (in)	41.0	Yes	Ramp XSlope (%)	1.2	
Places Providence	1000		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	- all		N/A	Flare Slope LT (%) N/A	N/A	Flare Slope RT (%)	N/A	
The second second	m 1		N/A	Flare Traversab	le LT? N/A	N/A	Flare Traversable RT?	N/A	
A A A A A A A A A A A A A A A A A A A	and		N/A	Landing Length	(in) N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:	N/A	Landing Width (i	in) N/A	N/A	DWS Contrast?	N/A	
	and and	N/A	N/A	Landing Slope (%) N/A	N/A	DWS Length (in)	N/A	
	a sound		N/A	Landing X Slope	e (%) N/A	N/A	DWS Full Width?	N/A	
	- WALL		N/A	Landing Curb? (Y/N) N/A	N/A	DWS Offset (in)	N/A	
	-		N/A	Shared Landing	? N/A				
6.16 1 1 T		PROW/ADA:	N/A	Gutter Ponding	? N/A	N/A	Gutter Slope (%)	N/A	
ALL AND A DESK	1	R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in		N/A	Gutter X Slope (%)	N/A	
	E T		N/A	Painted X Walk1		N/A	Painted X Walk2?	N/A	
	-			X Walk 1 Directi	on To NW		X Walk 2 Direction	N/A	
		1	N/A	X Walk 1 Width	(in) N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MOSS RD	-		X Walk 1 Slope	. ,		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign			X Walk 1 X Slop			X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A		N/A	Ramp inside XV	/alk1? N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A	
				Road X Slope (%		N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstruction		N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 18	850.00	Obstruction Typ	e		Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

