

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	ersection ID: N/A Main Street: SANDY_PORTER_RD			Cross Street: SHUTTERFLY_RD			Location:	SE		
ADA ID: FF558B0D0B4F	A ID: FF558B0D0B4F Ramp Type: Directional2		Initial	Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Commune .	Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ram	<b>p</b> .	N/A	Ramp Length (in)	132.0	N/A	Grade Break?	N/A	
	and in the		•	Yes	Ramp Width (in)	144.0	N/A	Grade Break Slope (%)	0.0	
				Yes	Ramp Slope (%)	0.5	N/A	Grade Break XSlope (%)	0.0	
				No	Ramp XSlope (%)	2.3				
		5		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		2		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Control 1	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	2		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	0.9	
Street 1 Name SHUT	TERFLY RD	_			X Walk 1 Direction	To NW		Road X Slope (%)	2.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.8	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1800.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	8.5	

