

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.1

2.6

N/A

Good

**Cross Street: CHARLOTTETOWNE AV** Intersection ID: 13947 Main Street: CHERRY ST Location: NE 10 ADA ID: FF73A1D4DEB1 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

60.0

47.5

N/A

Yes

To W

112.0

3.2

4.2

Yes

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 

Flare Traversable LT?



**CHERRY ST** Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compli	ance	Description
Remove & Replace Entire Ramp.	N/A	Ramp	Length (in)
·	No	Ramp	Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L1
	N/A	Landi	ng Length (in)
Surveyor Notes:	N/A	Landi	ng Width (in)
N/A	N/A	Landi	ng Slope (%)
	N/A	Landi	ng X Slope (%
	N/A	Landi	ng Curb? (Y/N
	N/A	Share	d Landing?
PROW/ADA:	N/A	Gutte	r Ponding?
Not Found, R304.5.1, R304.5.3	N/A	Gutte	r Lip Ht (in)
	N/A	Painte	ed X Walk1?
		X Wal	k 1 Direction
	N/A	X Wal	k 1 Width (in)
		X Wal	k 1 Slope (%)
		X Wal	k 1 X Slope (%
	N/A	Ramp	inside XWalk
		Road	Slope (%)



Total Cost:



N/A

1850.00

