

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

66.0

47.0

8.2

1.9

7.6

4.1

N/A

Good

12.4

Intersection ID: 31765 Main Street: FIRST_RUN_CT Cross Street: PINYON_PINE_LN Location: N

ADA ID: FF8EFD16F2A9 Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

N/A

No

N/A N/A

N/A N/A N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

69.5

46.0

2.6

3.0

84.5 Yes

44.0 No



Street 1 Name
YieldSign
Stop Condition-Street 1
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

LT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.5.3

Total Cost:



1600.00

Flare Type LT	N/A	N/A	Flare Type RT	N/A
Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
[1] [1] [1] [1] [1] [1] [1] [1] [1] [1]		N/A	Any Obstruction?	N/A
The state of the s			Obstruction Type	
				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	
	Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)	Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? N/A Road Slope (%) N/A	Flare Slope LT (%) Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%)	Flare Slope LT (%) Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) N/A Landing Curb? (Y/N) N/A Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) X Walk 2

Yes