


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10029624	Main Street: KING LOUIS CT	Cross Street: N/A	Location: NW
ADA ID: FF98D998DA42	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 36.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	64.0	Yes
			No	Ramp Width (in)	25.0	No
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To S	
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	0.1	
				X Walk 1 X Slope (%)	1.6	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.5.3</p>				Description	Data	
			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	N/A	N/A
			N/A	Flare Traversable RT?	N/A	N/A
			N/A	DWS Provided?	N/A	N/A
			N/A	DWS Contrast?	N/A	N/A
			N/A	DWS Length (in)	N/A	N/A
			N/A	DWS Full Width?	N/A	N/A
			N/A	DWS Offset (in)	N/A	N/A
			N/A	Gutter Slope (%)	N/A	N/A
			N/A	Gutter X Slope (%)	N/A	N/A
			N/A	Painted X Walk2?	No	N/A
				X Walk 2 Direction	To E	
			N/A	X Walk 2 Width (in)	N/A	N/A
				X Walk 2 Slope (%)	0.0	
				X Walk 2 X Slope (%)	1.6	
			N/A	Ramp inside XWalk2?	N/A	N/A
			N/A	Clear Space?	N/A	N/A
			N/A	Clear Space to XWalk (in)	N/A	N/A
			N/A	Storm Grate/Utility Hazard?	N/A	N/A
<p>Total Cost:</p> <p>\$ 3200.00</p>				Obstruction Type		
			N/A			N/A
						Yes
						Good

