

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49797Main Street:ATKINS\_RIDGE\_DRCross Street:PARSIFAL\_LNLocation:WADA ID: FFC54C866B2ERamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:1.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name ATKINS RIDGE DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:
Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

PROW/ADA:
Not Found

Total Cost: \$ 1850.00

| Field Measurements/Component Compliance |     |                       |                          |     |                             |      |
|---|-----|-----------------------|--------------------------|-----|-----------------------------|------|
| Compliance Description                  |     | Data                  | a Compliance Description |     | Data                        |      |
|   | N/A | Ramp Length (in)      | 48.0                     | Yes | Ramp Slope (%)              | 7.2  |
|   | Yes | Ramp Width (in)       | 48.0                     | Yes | Ramp XSlope (%)             | 2.4  |
|   | N/A | Flare Type LT         | N/A                      | N/A | Flare Type RT               | N/A  |
|   | N/A | Flare Slope LT (%)    | N/A                      | N/A | Flare Slope RT (%)          | N/A  |
|   | N/A | Flare Traversable LT? | N/A                      | N/A | Flare Traversable RT?       | N/A  |
|   | N/A | Landing Length (in)   | N/A                      | N/A | DWS Provided?               | N/A  |
|   | N/A | Landing Width (in)    | N/A                      | N/A | DWS Contrast?               | N/A  |
|   | N/A | Landing Slope (%)     | N/A                      | N/A | DWS Length (in)             | N/A  |
|   | N/A | Landing X Slope (%)   | N/A                      | N/A | DWS Full Width?             | N/A  |
|   | N/A | Landing Curb? (Y/N)   | N/A                      | N/A | DWS Offset (in)             | N/A  |
|   | N/A | Shared Landing?       | N/A                      |     |                             |      |
|   | N/A | Gutter Ponding?       | N/A                      | N/A | Gutter Slope (%)            | N/A  |
|   | N/A | Gutter Lip Ht (in)    | N/A                      | N/A | Gutter X Slope (%)          | N/A  |
|   | N/A | Painted X Walk1?      | No                       | N/A | Painted X Walk2?            | N/A  |
|   |     | X Walk 1 Direction    | To SE                    |     | X Walk 2 Direction          | N/A  |
|   | N/A | X Walk 1 Width (in)   | N/A                      | N/A | X Walk 2 Width (in)         | N/A  |
|   |     | X Walk 1 Slope (%)    | 4.2                      |     | X Walk 2 Slope (%)          | N/A  |
|   |     | X Walk 1 X Slope (%)  | 3.9                      |     | X Walk 2 X Slope (%)        | N/A  |
|   | N/A | Ramp inside XWalk1?   | N/A                      | N/A | Ramp inside XWalk2?         | N/A  |
|   |     | Road Slope (%)        | N/A                      | N/A | Clear Space?                | N/A  |
|   |     | Road X Slope (%)      | N/A                      | N/A | Clear Space to XWalk (in)   | N/A  |
|   | N/A | Any Obstructions?     | N/A                      | N/A | Storm Grate/Utility Hazard? | N/A  |
|   |     | Obstruction Type      |                          |     | Storm Grate/Utility Type    |      |
|   |     |                       | N/A                      |     |                             | N/A  |
|   |     |                       |                          | Yes | Surface Condition? (G/P)    | Good |
|   |     |                       |                          |     |                             |      |





