


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18769Main Street:BARCLAY_DOWNS_DRCross Street:RUNNYMEDE_LNLocation:NEADA ID: FFF8769DD6F0Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	RUNNYMEDE LN
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
PROW/ADA:					
Not Found, R304.2.2, R304.5.3					
Not 1 outlu, R304.2.2, R304.3.3					

Total Cost:



1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	120.0	No	Ramp Slope (%)	10.4		
Yes	Ramp Width (in)	68.0	No	Ramp XSlope (%)	7.8		
N/A	Flare Type LT	N/A	N/A	N/A Flare Type RT			
N/A	Flare Slope LT (%)	N/A	N/A	N/A Flare Slope RT (%)			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	133.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	6.2		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
All							