cole

N/A B 1 Tone Audible Range?

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



2.0 N/A B 2 Diameter (in)

N/A

| (| | | | | | | | | |
|--|--------------------------------|--|-----------------------|--|----------------------------|--------------------|---------------------|-------------------|-------------------|
| Intersection ID: N/A | Main Street: Cross Street: N/A | | | | | | Location: N/A | | |
| ADA ID: 040637E95F6D Signal Type:One Push Button-Non APS O | | | Overall C | ompliance: No | Severity Score: BT | N 1:N/ | A BTN 2: N/A | No BTN: | N/A |
| Codes | | Field Measurements/Component Compliance | | | | | | | |
| a line in the | | Baasible Calutional Bankasa Cia | | Compliance Desc | ription Data | a Con | npliance Descript | ion | Data |
| 1 4 4 4 4 | · · · · | Possible Solutions: Replace Sig Button With APS Button on New | | Button Count | Butto | n1 N/A | Distant to Addition | al Button (in) | N/A |
| 1 9 9 9 1 | Carl and a second | Remove & Relocate Sign. | | Additional Button Present? | | No | Additional Button | D | N/A |
| | | | | N/A Signal Buttons Required? | | /A N/A | Additional Ped Po | sts Required | N/A |
| 033 | | 6 | | How Many Ped | Street Xings? | / A | Located In An Isla | nd/Median? | N/A |
| | 9 . X | Surveyor Notes: BUTTON IS CC | MPLETELY | N/A B 1 Sign Preser | nt? Y | es N/A | B 2 Sign Present? | | N/A |
| 1. 1. 1. 1. | | INACCESSIBLE TO HANDICAPE | PED | Yes B1 Sign Purpose? | | es N/A | B 2 Sign Purpose | ? | N/A |
| | | | | Yes B 1 Sign Letterin | ng & Contrast? Y | es N/A | B 2 Sign Lettering | & Contrast? | N/A |
| | | 4 | | Yes B 1 Parallel To XWalk? | | es N/A | B 2 Parallel To XV | /alk? | N/A |
| | ach i s | PROW/ADA: TMUTCD 4e.08, R4 | 04.2, R404.3, | Yes B 1 PAR to Butte | on? Y | es N/A | B 2 PAR to Button | ? | N/A |
| | R404.7.3, R404.7.2 | | Yes B 1 PAR to XWalk? | | es N/A | B 2 PAR to XWalk | ? | N/A | |
| | 8 | Yes B1Cle | | Space? Y | es N/A | B 2 Clear Floor Sp | bace? | N/A | |
| | | | | N/A B1 FWD Approach? | | No N/A | B 2 FWD Approac | h? | N/A |
| Total Cost: \$ 65 | | | | 0 N/A B 1 FWD Approach Constrained? | | /A N/A | B 2 FWD Approac | h Constrained? | N/A |
| | | | | N/A B 1 FWD Approa | ach Reach (in) N | /A N/A | B 2 FWD Approac | h Reach (in) | N/A |
| | | | | N/A B 1 FWD Approach Width (in) | | /A N/A | B 2 FWD Approac | h Width (in) | N/A |
| | | | | N/A B1 FWD Approach Obstruction? | | No N/A | B 2 FWD Approac | h Obstruction? | N/A |
| | | | | N/A B 1 FWD Approach Obstruction Dist (i | | /A N/A | B 2 FWD Approac | h ObstructionDist | (in) N/A |
| | | | | N/A B 1 PARA Appro | bach? Y | es N/A | B 2 PARA Approa | ch? | N/A |
| | | | 17 | N/A B 1 PARA Appro | bach Constrained? Y | es N/A | B 2 PARA Approa | ch Constrained? | N/A |
| | | | | No B 1 PARA Appro | bach Reach (in) 8 | 5.0 N/A | B 2 PARA Approa | ch Reach (in) | N/A |
| | | | | No B 1 PARA Appro | bach Width (in) 4 | 3.0 N/A | B 2 PARA Approa | ch Width (in) | N/A |
| | | | | N/A B 1 PARA Approach Obstruction? | | No N/A | B 2 PARA Approa | ch Obstruction? | N/A |
| APS Compliance | | | | N/A B 1 PARA Appro | bach Obstruction Dist (in) | /A N/A | B 2 PARA Approa | ch ObstructionDis | t (in) N/A |
| Is Button 1 APS or Non-APS? | NonAPS | Is Button 2 APS or Non-APS? | N/A | No B 1 Clear Floor | Space Slope (%) | /A N/A | B 2 Clear Floor Sp | bace Slope (%) | N/A |
| N/A B 1 VibroTact Arrow? | | A B 2 VibroTact Arrow? | N/A | No B 1 Clear Floor | , | | B 2 Clear Floor Sp | , | N/A |
| N/A B 1 VibroTact Parallel to Xing? | | A B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope | | | B 2 PAR Slope (% | | N/A |
| N/A B 1 VibroTact Contrast | | A B 2 VibroTact Contrast | N/A | Yes B1 Height (in) | | | B 2 Height (in) | | N/A |
| N/A B 1 Pilot Light? | | A B 2 Pilot Light? | N/A | Yes B 1 Pressure (# |) | 2.0 N/A | B 2 Pressure (#) | | N/A |
| N/A B 1 Pilot Light Illumination? | | A B 2 Pilot Light Illumination? | N/A | Yes B 1 Closed Fist | • | • | B 2 Closed Fist O | peration? | N/A |
| N/A B 1 Verbal Walk Cycle? | | A B 2 Verbal Walk Cycle? | - | | | | pliance | | |
| N/A B 1 Verbal Message Audible? | | A B 2 Verbal Message Audible? | N/A | N/A B1 Clear Xing | | | B 2 Clear Xing Dir | | N/A |
| N/A B 1 Locator Tone? | | A B 2 Locator Tone? | N/A | B 1 Crossing Di | | | B 2 Crossing Dire | | N/A |
| N/A B 1 Percussive Walk Cycle? | | A B 2 Percussive Walk Cycle? | N/A | No B 1 DistanceTo | | | B 2 DistanceTo X | | N/A |
| N/A B 1 Extended Press Feature? | N/A N/ | A B 2 Extended Press Feature? | N/A | No B 1 DistanceTo | Curb (in) 13 | 1.0 N/A | B 2 DistanceTo Cu | urb (in) | N/A |

N/A

Yes B 1 Diameter (in)

N/A N/A B 2 Tone Audible Range?