

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A No

N/A N/A N/A

N/A N/A N/A

N/A N/A N/A N/A N/A N/A N/A N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 07105ADD459E Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

Additional Button Present?

N/A Signal Buttons Required?

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Data



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.3, R404.2

Total Cost: \$ 650.00

J 030.0

N/A

N/A



N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

		•			•
		How Many Ped Street Xings?	1		Located In An Island/Median?
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?
	Yes	B 1 PAR to Button?	No	N/A	B 2 PAR to Button?
	No	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWD Approach?
)	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)
	N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?
١	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)
l	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?
l	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?
	Yes	B 1 PARA Approach Reach (in)	0.0	N/A	B 2 PARA Approach Reach (in)
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)
	N/A	B 1 PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?
	N/A	B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach ObstructionDist (in
	Yes	B 1 Clear Floor Space Slope (%)	0.9	N/A	B 2 Clear Floor Space Slope (%)

7	1	
	- La	
		-
1		

	APS Compliance									
	Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A						
N/A	B 1 VibroTact Arrow?	N/A N	A B 2 VibroTact Arrow?	N/A						
N/A	B 1 VibroTact Parallel to Xing?	N/A N	A B 2 VibroTact Parallel to Xing?	N/A						
N/A	B 1 VibroTact Contrast	N/A N	A B 2 VibroTact Contrast	N/A						
N/A	B 1 Pilot Light?	N/A N	A B 2 Pilot Light?	N/A						
N/A	B 1 Pilot Light Illumination?	N/A N	A B 2 Pilot Light Illumination?	N/A						
N/A	B 1 Verbal Walk Cycle?	N/A N	A B 2 Verbal Walk Cycle?	N/A						
N/A	B 1 Verbal Message Audible?	N/A N	A B 2 Verbal Message Audible?	N/A						
N/A	B 1 Locator Tone?	N/A N	A B 2 Locator Tone?	N/A						
N/A	B 1 Percussive Walk Cycle?	N/A N	A B 2 Percussive Walk Cycle?	N/A						

(in) N/A									
N/A									
N/A									
N/A									
N/A									
N/A									
N/A									
MUTCD Compliance									
N/A									
N/A									
N/A									
N/A									
N/A									