

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

204.0

N/A

N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: 0A2B0D1FE90E Signal Type: One Push Button-Non APS **Overall Compliance: No** N/A

Compliance Description

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Data



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R410.6

Total Cost:

700.0



		Additional Button Present?	Yes		Additional Button ID EDED370D	9E88
	N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required	N/A
		How Many Ped Street Xings?	2		Located In An Island/Median?	No
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	N/A
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A
	No	B 1 Sign Lettering & Contrast?	No	N/A	B 2 Sign Lettering & Contrast?	N/A
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWD Approach?	N/A
00	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
Ë	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A
	Yes	B 1 PARA Approach Reach (in)	8.0	N/A	B 2 PARA Approach Reach (in)	N/A
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)	8.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Yes	B 1 Clear Floor Space Slope (%)	0.1	N/A	B 2 Clear Floor Space Slope (%)	N/A
	Yes	B 1 Clear Floor Space XSlope (%)	0.5	N/A	B 2 Clear Floor Space XSlope (%)	N/A
	N/A	B 1 PAR Slope (%)	1.2	N/A	B 2 PAR Slope (%)	N/A
	Yes	B 1 Height (in)	40.5	N/A	B 2 Height (in)	N/A



APS Compliance

N/A	B 1 VibroTact Arrow?
N/A	B 1 VibroTact Parallel to Xing?
N/A	B 1 VibroTact Contrast
N/A	B 1 Pilot Light?
N/A	B 1 Pilot Light Illumination?

Is Button 1 APS or Non-APS?

N/A B 1 Verbal Walk Cycle?

N/A B 1 Verbal Message Audible? N/A B 1 Locator Tone?

N/A B 1 Percussive Walk Cycle? N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

NonAPS Is Button 2 APS or Non-APS? N/A N/A N/A B 2 VibroTact Arrow? N/A N/A B 2 VibroTact Parallel to Xing? N/A N/A B 2 VibroTact Contrast N/A N/A N/A B 2 Pilot Light? N/A **N/A** B 2 Pilot Light Illumination? N/A N/A B 2 Verbal Walk Cycle? N/A N/A N/A B 2 Verbal Message Audible? N/A N/A B 2 Locator Tone?

N/A B 2 Percussive Walk Cycle?

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

N/A N/A N/A N/A N/A Yes B 1 Diameter (in)

No B 1 Clear Xing Direction? **B 1 Crossing Direction** Yes B 1 DistanceTo XWalk (in) No B 1 DistanceTo Curb (in)

Yes B 1 Pressure (#)

Yes B 1 Closed Fist Operation?

To NW

MUTCD Compliance

2.0 N/A B 2 Pressure (#)

Yes N/A B 2 Closed Fist Operation?

NotClearlyMarked N/A B 2 Clear Xing Direction? **B 2 Crossing Direction** 0.0 N/A B 2 DistanceTo XWalk (in)

135.0 N/A B 2 DistanceTo Curb (in) 2.0 N/A B 2 Diameter (in)