

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

Location: N/A Intersection ID: N/A **Main Street:** Cross Street: N/A

Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 0C433AD40247

Compliance Description

Additional Button Present? N/A Signal Buttons Required?

Yes B 1 Sign Lettering & Contrast?

How Many Ped Street Xings?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

No N/A B 2 FWD Approach?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

N/A



Possible Solutions: Remove and Replace Clear Space. Surveyor Notes: N/A

PROW/ADA: R404.2, R404.3

	The state of the s	The second second							
			Total Cost:	400.00	N/A B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
	***	N/A B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A			
				T	N/A B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
				N/A B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A	
				N/A B 1 FWD Approach Obstruction Dist (in)	3.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A	
					N/A B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
					N/A B 1 PARA Approach Constrained?	Yes	N/A	B 2 PARA Approach Constrained?	N/A
					Yes B 1 PARA Approach Reach (in)	6.0	N/A	B 2 PARA Approach Reach (in)	N/A
					Yes B 1 PARA Approach Width (in)	60.0	N/A	B 2 PARA Approach Width (in)	N/A
					N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance					N/A B 1 PARA Approach Obstruction Dist (in)	3.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%)	7.7	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A	B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)	0.2	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A	B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	N/A	N/A	B 2 PAR Slope (%)	N/A
N/A	B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	41.0	N/A	B 2 Height (in)	N/A
N/A	B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	1.0	N/A	B 2 Pressure (#)	N/A
N/A	B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A	B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A	B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	N/A B 1 Clear Xing Direction?	Yes	N/A	B 2 Clear Xing Direction?	N/A
N/A	B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	To W		B 2 Crossing Direction	N/A
N/A	B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A
N/A	B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo Curb (in)	69.0	N/A	B 2 DistanceTo Curb (in)	N/A
N/A	B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)	2.0	N/A	B 2 Diameter (in)	N/A