

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

9575711E99E2

550.0

N/A

No

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A **ADA ID: 19AE6AEFA413**

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 1/2

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R404.3, R404.7.3

Total Cost:

700.00



ADS Compliance



| | N/A | B 1 Sign Present? | Yes | N/A | B 2 Sign Present? | N/A |
|------------------|-----|---|-------|-----|--|-----|
| , | Yes | B 1 Sign Purpose? | Yes | N/A | B 2 Sign Purpose? | N/A |
| | No | B 1 Sign Lettering & Contrast? | No | N/A | B 2 Sign Lettering & Contrast? | N/A |
| , | Yes | B 1 Parallel To XWalk? | Yes | N/A | B 2 Parallel To XWalk? | N/A |
| , | Yes | B 1 PAR to Button? | Yes | N/A | B 2 PAR to Button? | N/A |
| , | Yes | B 1 PAR to XWalk? | Yes | N/A | B 2 PAR to XWalk? | N/A |
| , | Yes | B 1 Clear Floor Space? | Yes | N/A | B 2 Clear Floor Space? | N/A |
| | N/A | B 1 FWD Approach? | No | N/A | B 2 FWD Approach? | N/A |
|) | N/A | B 1 FWD Approach Constrained? | N/A | N/A | B 2 FWD Approach Constrained? | N/A |
| | N/A | B 1 FWD Approach Reach (in) | N/A | N/A | B 2 FWD Approach Reach (in) | N/A |
| | N/A | B 1 FWD Approach Width (in) | N/A | N/A | B 2 FWD Approach Width (in) | N/A |
| | N/A | B 1 FWD Approach Obstruction? | N/A | N/A | B 2 FWD Approach Obstruction? | N/A |
| | N/A | B 1 FWD Approach Obstruction Dist (in) | N/A | N/A | B 2 FWD Approach ObstructionDist (in) | N/A |
| | N/A | B 1 PARA Approach? | Yes | N/A | B 2 PARA Approach? | N/A |
| | N/A | B 1 PARA Approach Constrained? | No | N/A | B 2 PARA Approach Constrained? | N/A |
| | No | B 1 PARA Approach Reach (in) | 14.0 | N/A | B 2 PARA Approach Reach (in) | N/A |
| | N/A | B 1 PARA Approach Width (in) | N/A | N/A | B 2 PARA Approach Width (in) | N/A |
| | N/A | B 1 PARA Approach Obstruction? | Yes | N/A | B 2 PARA Approach Obstruction? | N/A |
| | N/A | B 1 PARA Approach Obstruction Dist (in) | 10.0 | N/A | B 2 PARA Approach ObstructionDist (in) | N/A |
| | No | B 1 Clear Floor Space Slope (%) | 3.2 | N/A | B 2 Clear Floor Space Slope (%) | N/A |
| | No | B 1 Clear Floor Space XSlope (%) | 2.1 | N/A | B 2 Clear Floor Space XSlope (%) | N/A |
| | N/A | B 1 PAR Slope (%) | 0.4 | N/A | B 2 PAR Slope (%) | N/A |
| , | Yes | B 1 Height (in) | 41.0 | N/A | B 2 Height (in) | N/A |
| , | Yes | B 1 Pressure (#) | 2.0 | N/A | B 2 Pressure (#) | N/A |
| , | Yes | B 1 Closed Fist Operation? | Yes | N/A | B 2 Closed Fist Operation? | N/A |
| MUTCD Compliance | | | | | | |
| , | Yes | B 1 Clear Xing Direction? ClearlyMa | arked | N/A | B 2 Clear Xing Direction? | N/A |
| | | B 1 Crossing Direction T | o SW | | B 2 Crossing Direction | N/A |
| , | Yes | B 1 DistanceTo XWalk (in) | 0.0 | N/A | B 2 DistanceTo XWalk (in) | N/A |
| - | No | B 1 DistanceTo Curb (in) | 105.0 | N/A | B 2 DistanceTo Curb (in) | N/A |

| | | APS Com | pııan | ce |
|-------------------|---------------------------|---------|-------|-------------|
| Is Butte | on 1 APS or Non-APS? | NonAPS | | Is Button |
| N/A B1 Vil | oroTact Arrow? | N/A | N/A | B 2 Vibro |
| N/A B 1 Vik | oroTact Parallel to Xing? | N/A | N/A | B 2 Vibro |
| N/A B1 Vil | oroTact Contrast | N/A | N/A | B 2 Vibro |
| N/A B1Pil | ot Light? | N/A | N/A | B 2 Pilot |
| N/A B 1 Pil | ot Light Illumination? | N/A | N/A | B 2 Pilot I |
| N/A B 1 Ve | rbal Walk Cycle? | N/A | N/A | B 2 Verba |
| N/A B 1 Ve | rbal Message Audible? | N/A | N/A | B 2 Verba |
| N/A B1Lo | cator Tone? | N/A | N/A | B 2 Locat |
| N/A B 1 Pe | rcussive Walk Cycle? | N/A | N/A | B 2 Percu |
| N/A B1Ex | tended Press Feature? | N/A | N/A | B 2 Exter |

N/A B 1 Tone Audible Range?

| APS | | Is Button 2 APS or Non-APS? | N/A |
|-----|-----|---------------------------------|-----|
| N/A | N/A | B 2 VibroTact Arrow? | N/A |
| N/A | N/A | B 2 VibroTact Parallel to Xing? | N/A |
| N/A | N/A | B 2 VibroTact Contrast | N/A |
| N/A | N/A | B 2 Pilot Light? | N/A |
| N/A | N/A | B 2 Pilot Light Illumination? | N/A |
| N/A | N/A | B 2 Verbal Walk Cycle? | N/A |
| N/A | N/A | B 2 Verbal Message Audible? | N/A |
| N/A | N/A | B 2 Locator Tone? | N/A |
| N/A | N/A | B 2 Percussive Walk Cycle? | N/A |
| N/A | N/A | B 2 Extended Press Feature? | N/A |
| N/A | N/A | B 2 Tone Audible Range? | N/A |

| Yes B 1 Closed Fist Operation? | Yes N/A | B 2 Closed Fist Operati | | |
|--------------------------------|-------------------|--------------------------|--|--|
| | MUTCD Compliance | | | |
| Yes B 1 Clear Xing Direction? | ClearlyMarked N/A | B 2 Clear Xing Direction | | |
| B 1 Crossing Direction | To SW | B 2 Crossing Direction | | |
| Yes B 1 DistanceTo XWalk (in) | | B 2 DistanceTo XWalk (| | |
| No B 1 DistanceTo Curb (in) | 105.0 N/A | B 2 DistanceTo Curb (ir | | |
| Yes B 1 Diameter (in) | 2.0 N/A | B 2 Diameter (in) | | |