cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



| Intersection ID: N/A | Main Street: | | | Cross Street: N/A | | Location: N/A | |
|--|---|--------------------------------------|----------------------------|---|--------------------------|------------------------------------|------------------------|
| ADA ID: 1A56AF14550E | Signal Type:O | ne Push Button-Non APS | Overall Co | ompliance: No Severity | Score: BTN 1:N | A BTN 2: N/A No BTN | : N/A |
| Codes/ | Mitigation Info | /Possible Solution | Field Mea | Field Measurements/Component Compliance | | | |
| Possible Solutions: Remove and Replace | | | Panlaga | Compliance Description | | | |
| | | Clear Space. | ve and Replace | Button Count | Button1 Ye | s Distant to Additional Button (in |) 198.0 |
| A A | | | Additional Button Present? | Yes | Additional Button ID | 4A27325305FE | |
| State 1 | | Surveyor Notes: N/A | | N/A Signal Buttons Required? | N/A N// | Additional Ped Posts Required | N/A |
| | | | | How Many Ped Street Xings? | N/A | Located In An Island/Median? | N/A |
| - NEE | | | | N/A B 1 Sign Present? | Yes N// | A B 2 Sign Present? | N/A |
| the again the second second | | | | Yes B 1 Sign Purpose? | Yes N/ | A B 2 Sign Purpose? | N/A |
| | | | | Yes B 1 Sign Lettering & Contrast? | Yes N/ | A B 2 Sign Lettering & Contrast? | N/A |
| 1111/2000 | tes (| | | Yes B 1 Parallel To XWalk? | Yes N/ | A B 2 Parallel To XWalk? | N/A |
| | 1 Part 1 | PROW/ADA: R406.2, R404.7.3, R404.7.2 | | Yes B 1 PAR to Button? | Yes N// | A B 2 PAR to Button? | N/A |
| CIII Comment | 1//01 | | | Yes B 1 PAR to XWalk? | Yes N// | A B 2 PAR to XWalk? | N/A |
| 1/ / / / / And | | | Yes B 1 Clear Floor Space? | Yes N/ | A B 2 Clear Floor Space? | N/A | |
| | | | | N/A B1 FWD Approach? | Yes N/ | A B 2 FWD Approach? | N/A |
| An 11 Star 11 A | | Total Cost: \$ | 400.00 | N/A B 1 FWD Approach Constrained | d? Yes N// | A B 2 FWD Approach Constraine | ed? N/A |
| | | | | No B1 FWD Approach Reach (in) | 18.0 N// | A B 2 FWD Approach Reach (in) | N/A |
| | | | Aluellan. | Yes B1 FWD Approach Width (in) | 48.0 N// | A B 2 FWD Approach Width (in) | N/A |
| | | | Martin and | N/A B 1 FWD Approach Obstruction | n? Yes N/ | A B 2 FWD Approach Obstructio | n? N/A |
| | | | | N/A B1 FWD Approach Obstruction | n Dist (in) 2.0 N/ | A B 2 FWD Approach Obstructio | nDist (in) N/A |
| | | | | N/A B 1 PARA Approach? | Yes N// | A B 2 PARA Approach? | N/A |
| | | | | N/A B 1 PARA Approach Constraine | ed? Yes N/ | A B 2 PARA Approach Constrain | ed? N/A |
| | | | | No B 1 PARA Approach Reach (in) | 18.0 N// | A B 2 PARA Approach Reach (in |) N/A |
| | | | | No B 1 PARA Approach Width (in) | 48.0 N// | A B 2 PARA Approach Width (in) | N/A |
| | | | | N/A B 1 PARA Approach Obstructio | n? Yes N/ | A B 2 PARA Approach Obstruction | on? N/A |
| APS Compliance | | | | N/A B 1 PARA Approach Obstructio | n Dist (in) 2.0 N/ | A B 2 PARA Approach Obstruction | onDist (in) N/A |
| Is Button 1 APS or Non-APS? | NonAPS | Is Button 2 APS or Non-APS? | N/A | Yes B 1 Clear Floor Space Slope (% | %) 0.9 N// | A B 2 Clear Floor Space Slope (| %) N/A |
| N/A B 1 VibroTact Arrow? | N/A N/A | B 2 VibroTact Arrow? | N/A | Yes B 1 Clear Floor Space XSlope | (%) 0.6 N// | A B 2 Clear Floor Space XSlope | (%) N/A |
| N/A B1 VibroTact Parallel to Xing? | N/A N/A | B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope (%) | N/A N// | A B 2 PAR Slope (%) | N/A |
| N/A B 1 VibroTact Contrast | N/A N/A | B 2 VibroTact Contrast | N/A | Yes B 1 Height (in) | 40.0 N// | A B 2 Height (in) | N/A |
| N/A B 1 Pilot Light? | N/A N/A | B 2 Pilot Light? | N/A | Yes B 1 Pressure (#) | 2.0 N// | A B 2 Pressure (#) | N/A |
| N/A B 1 Pilot Light Illumination? | N/A N/A | B 2 Pilot Light Illumination? | N/A | Yes B1 Closed Fist Operation? | Yes N// | A B 2 Closed Fist Operation? | N/A |
| N/A B 1 Verbal Walk Cycle? | I/A B 1 Verbal Walk Cycle? N/A N/A B 2 Verbal Walk Cycle? N/A | | N/A | MUTCD Compliance | | | |
| N/A B 1 Verbal Message Audible? | N/A N/A | B 2 Verbal Message Audible? | N/A | N/A B1 Clear Xing Direction? | Yes N// | A B 2 Clear Xing Direction? | N/A |
| N/A B 1 Locator Tone? | N/A N/A | B 2 Locator Tone? | N/A | B 1 Crossing Direction | To NW | B 2 Crossing Direction | N/A |
| N/A B 1 Percussive Walk Cycle? | N/A N/A | B 2 Percussive Walk Cycle? | N/A | Yes B1 DistanceTo XWalk (in) | 41.0 N// | A B 2 DistanceTo XWalk (in) | N/A |
| N/A B 1 Extended Press Feature? | N/A N/A | B 2 Extended Press Feature? | N/A | Yes B 1 DistanceTo Curb (in) | 32.0 N// | A B 2 DistanceTo Curb (in) | N/A |
| N/A B 1 Tone Audible Range? | N/A N/A | B 2 Tone Audible Range? | N/A | Yes B1 Diameter (in) | 2.0 N// | A B 2 Diameter (in) | N/A |