

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Intersection ID: N/A Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 1DFAEDD52F5D **Overall Compliance: No**

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

No B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space? N/A B 1 FWD Approach?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

No N/A B 2 Sign Purpose?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

Located In An Island/Median?

Data



Possible Solutions: Remove & Replace Sign. Provide Push Button Extension. Remove and Replace Clear Space.

Surveyor Notes: N/A

PROW/ADA: R209.1, TMUTCD 4e.08, R404.2, R406.2

1150.00 N/A B 1 FWD Approach Constrained? Total Cost:





			No B 1 FWD Approach Reach (in)	9.0 N/A	B 2 FWD Approach Reach (in)	N/A
			N/A B 1 FWD Approach Width (in)	60.0 N/A	B 2 FWD Approach Width (in)	N/A
			N/A B 1 FWD Approach Obstruction?	Yes N/A	B 2 FWD Approach Obstruction?	N/A
			N/A B 1 FWD Approach Obstruction Dist (in	7.0 N/A	B 2 FWD Approach ObstructionDist (in)	N/A
			N/A B 1 PARA Approach?	Yes N/A	B 2 PARA Approach?	N/A
			N/A B 1 PARA Approach Constrained?	No N/A	B 2 PARA Approach Constrained?	N/A
			Yes B 1 PARA Approach Reach (in)	9.0 N/A	B 2 PARA Approach Reach (in)	N/A
			N/A B 1 PARA Approach Width (in)	60.0 N/A	B 2 PARA Approach Width (in)	N/A
			N/A B 1 PARA Approach Obstruction?	Yes N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance			N/A B 1 PARA Approach Obstruction Dist (ir	n) 7.0 N/A	B 2 PARA Approach ObstructionDist (in) N/A
Is Button 1 APS or Non-APS?	NonAPS Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	0.3 N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	No N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	5.9 N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	No N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.5 N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	No N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	41.0 N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	No N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	1.5 N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	No N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	Verbal Walk Cycle? No N/A B 2 Verbal Walk Cycle? N/A		MUTCD Compliance			
N/A B 1 Verbal Message Audible?	No N/A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction? Clearly	Marked N/A	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	No N/A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To SW	B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	No N/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	45.0 N/A	B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Extended Press Feature?	No N/A B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo Curb (in)	68.0 N/A	B 2 DistanceTo Curb (in)	N/A
N/A B 1 Tone Audible Range?	No N/A B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)	2.0 N/A	B 2 Diameter (in)	N/A
N/A P 1 Tono Audible Pange?	No N/A R 2 Topo Audible Pange?	N/A	Vac P 1 Diameter (in)	2 0 N/A	P.2 Diameter (in)	