



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R406.2, R209.1, MUTCD 4e.10

Total Cost: \$ 650.00



| APS Compliance                      |     |
|-------------------------------------|-----|
| Is Button 1 APS or Non-APS?         | APS |
| Yes B 1 VibroTact Arrow?            | Yes |
| Yes B 1 VibroTact Parallel to Xing? | Yes |
| Yes B 1 VibroTact Contrast          | Yes |
| Yes B 1 Pilot Light?                | Yes |
| Yes B 1 Pilot Light Illumination?   | Yes |
| No B 1 Verbal Walk Cycle?           | Yes |
| N/A B 1 Verbal Message Audible?     | Yes |
| Yes B 1 Locator Tone?               | Yes |
| Yes B 1 Percussive Walk Cycle?      | Yes |
| Yes B 1 Extended Press Feature?     | Yes |
| Yes B 1 Tone Audible Range?         | Yes |

| MUTCD Compliance              |               |
|-------------------------------|---------------|
| Yes B 1 Clear Xing Direction? | ClearlyMarked |
| B 1 Crossing Direction        | To NE         |
| Yes B 1 DistanceTo XWalk (in) | 0.0           |
| No B 1 DistanceTo Curb (in)   | 85.0          |
| Yes B 1 Diameter (in)         | 2.0           |