

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

8CB3B4F62642

128.0

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

**Main Street:** Cross Street: N/A Location: N/A Intersection ID: N/A

Signal Type: One Push Button-APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: 389AD6341F26 **Overall Compliance: No** N/A

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 Yes** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

Yes



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: SIGNAL POWERED, BUT **CANT PUSH BUTTON** 

PROW/ADA: TMUTCD 4e.08, R404.2, R406.2, R209.1, TMUTCD 4e.10, MUTCD 4e.08, R104.2,

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Control of the Contro								
Market 1			Total Cost: \$	650.00	N/A	B 1 FWD Approach Constraine	ed? <b>No</b>	N/A	B 2 FWD Approach Constrained?	N/A
					No	B 1 FWD Approach Reach (in)	14.0	N/A	B 2 FWD Approach Reach (in)	N/A
					N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	RISON				N/A	B 1 FWD Approach Obstructio	n? <b>Yes</b>	N/A	B 2 FWD Approach Obstruction?	N/A
RK MORRISON by Apartment						B 1 FWD Approach Obstructio	n Dist (in) <b>8.0</b>	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
						B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
						B 1 PARA Approach Constrain	ed? <b>No</b>	N/A	B 2 PARA Approach Constrained?	N/A
						B 1 PARA Approach Reach (in	) <b>8.0</b>	N/A	B 2 PARA Approach Reach (in)	N/A
					N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
					N/A	B 1 PARA Approach Obstruction	on? Yes	N/A	B 2 PARA Approach Obstruction?	N/A
	APS Co	mplian	ce		N/A	B 1 PARA Approach Obstruction	on Dist (in) <b>5.0</b>	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
Is Button 1 APS	S or Non-APS? AP	s	Is Button 2 APS or Non-APS?	N/A	Yes	B 1 Clear Floor Space Slope (	%) 1.3	N/A	B 2 Clear Floor Space Slope (%)	N/A
No B 1 VibroTact A	Arrow? N	o N/A	B 2 VibroTact Arrow?	N/A	No	B 1 Clear Floor Space XSlope	(%) 2.3	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact F	Parallel to Xing? N/	A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A	B 1 PAR Slope (%)	2.1	N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact (	Contrast N/	A N/A	B 2 VibroTact Contrast	N/A	Yes	B 1 Height (in)	36.0	N/A	B 2 Height (in)	N/A
No B 1 Pilot Light?	? N	o N/A	B 2 Pilot Light?	N/A	Yes	B 1 Pressure (#)	3.0	N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light	Illumination? N/	A N/A	B 2 Pilot Light Illumination?	N/A	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle? No N/A B 2 Verbal Walk Cycle? N/A			N/A	MUTCD Compliance						
N/A B 1 Verbal Mes	ssage Audible? N/	A N/A	B 2 Verbal Message Audible?	N/A	Yes	B 1 Clear Xing Direction?	ClearlyMarked	N/A	B 2 Clear Xing Direction?	N/A
No B 1 Locator To	ne? N	o N/A	B 2 Locator Tone?	N/A		B 1 Crossing Direction	To NE		B 2 Crossing Direction	N/A
N/A B 1 Percussive	• Walk Cycle? N	o N/A	B 2 Percussive Walk Cycle?	N/A	No	B 1 DistanceTo XWalk (in)	82.0	N/A	B 2 DistanceTo XWalk (in)	N/A
No B 1 Extended F	Press Feature? N	o N/A	B 2 Extended Press Feature?	N/A	No	B 1 DistanceTo Curb (in)	119.0	N/A	B 2 DistanceTo Curb (in)	N/A
No B 1 Tone Audib	ole Range? N/	A N/A	B 2 Tone Audible Range?	N/A	Yes	B 1 Diameter (in)	2.0	N/A	B 2 Diameter (in)	N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

N/A B 1 FWD Approach?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?