

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 3AFC8FD47957

**Compliance Description** 

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

**N/A** B 1 FWD Approach Obstruction?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space? N/A B 1 FWD Approach?

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

6.0 N/A B 2 FWD Approach Reach (in)

Yes N/A B 2 FWD Approach Obstruction?

N/A N/A B 2 FWD Approach Width (in)

Located In An Island/Median?

Data

No



Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R406.2, R209.1, MUTCD 4e.10

Total Cost:

650.00 N/A B 1 FWD Approach Constrained?



Yes N/A B 2 Tone Audible Range?



			<ul><li>N/A B 1 FWD Approach Obstruction Dist (</li><li>N/A B 1 PARA Approach?</li><li>N/A B 1 PARA Approach Constrained?</li><li>Yes B 1 PARA Approach Reach (in)</li></ul>	Yes N/A No N/A	<ul><li>B 2 FWD Approach ObstructionDist (in)</li><li>B 2 PARA Approach?</li><li>B 2 PARA Approach Constrained?</li><li>B 2 PARA Approach Reach (in)</li></ul>	N/A N/A N/A N/A
The Part of	E SHAN TO BE THE		N/A B 1 PARA Approach Width (in)		B 2 PARA Approach Width (in)	N/A
			N/A B 1 PARA Approach Obstruction?	•	B 2 PARA Approach Obstruction?	N/A
APS Compliance			N/A B 1 PARA Approach Obstruction Dist	(in) <b>2.0 N/A</b>	B 2 PARA Approach ObstructionDist (in)	N/A
Is Button 1 APS or Non-APS?	APS Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%)	6.9 N/A	B 2 Clear Floor Space Slope (%)	N/A
Yes B 1 VibroTact Arrow?	Yes N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	3.4 N/A	B 2 Clear Floor Space XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	Yes N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	1.7 N/A	B 2 PAR Slope (%)	N/A
Yes B 1 VibroTact Contrast	Yes N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	37.0 N/A	B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	4.0 N/A	B 2 Pressure (#)	N/A
Yes B 1 Pilot Light Illumination?	Yes N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A
No B 1 Verbal Walk Cycle?	Yes N/A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance			
N/A B 1 Verbal Message Audible?	Yes N/A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction? Clear	lyMarked N/A	B 2 Clear Xing Direction?	N/A
Yes B 1 Locator Tone?	Yes N/A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To NE	B 2 Crossing Direction	N/A
Yes B 1 Percussive Walk Cycle?	Yes N/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	6.0 N/A	B 2 DistanceTo XWalk (in)	N/A
Yes B 1 Extended Press Feature?	Yes N/A B 2 Extended Press Feature?	N/A	No B 1 DistanceTo Curb (in)	96.0 N/A	B 2 DistanceTo Curb (in)	N/A

N/A

Yes B 1 Diameter (in)