

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

**Main Street:** Cross Street: N/A Location: N/A Intersection ID: N/A

ADA ID: 3F746A7E2160 Signal Type: One Push Button-APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

No B 1 Sign Lettering & Contrast?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Yes B 1 Parallel To XWalk?

No B 1 Clear Floor Space?

B 1 DistanceTo Curb (in)

No B 1 Diameter (in)

No B 1 FWD Approach?

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

No N/A B 2 Clear Floor Space? No N/A B 2 FWD Approach?

84.0 N/A B 2 DistanceTo Curb (in)

2.25 N/A B 2 Diameter (in)

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Additional Button ID

N/A N/A Additional Ped Posts Required

No N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

No



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 3/8"

PROW/ADA: R410.6. TMUTCD 4e.08. R404.1. R404.7.1, R404.7.2, DMS-11132, R209.1, MUTCD 4e.10,

Total Cost:

N/A

N/A



		- · · · · - · · · · · · · · · · · · · ·					
700.00	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A	
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A	
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A	
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A	
E	N/A	B 1 FWD Approach Obstruction Dist (in)	12.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A	
	No	B 1 PARA Approach?	No	N/A	B 2 PARA Approach?	N/A	
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A	
	N/A	B 1 PARA Approach Reach (in)	N/A	N/A	B 2 PARA Approach Reach (in)	N/A	
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A	
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A	
	N/A	B 1 PARA Approach Obstruction Dist (in)	12.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A	
N/A	N/A	B 1 Clear Floor Space Slope (%)	N/A	N/A	B 2 Clear Floor Space Slope (%)	N/A	
N/A	N/A	B 1 Clear Floor Space XSlope (%)	N/A	N/A	B 2 Clear Floor Space XSlope (%)	N/A	
N/A	N/A	B 1 PAR Slope (%)	N/A	N/A	B 2 PAR Slope (%)	N/A	
N/A	Yes	B 1 Height (in)	32.0	N/A	B 2 Height (in)	N/A	
N/A	Yes	B 1 Pressure (#)	2.5	N/A	B 2 Pressure (#)	N/A	
N/A	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A	
N/A	_	MUTCD Compliance					
N/A	Yes	B 1 Clear Xing Direction? ClearlyMa	arked	N/A	B 2 Clear Xing Direction?	N/A	
N/A		B 1 Crossing Direction	To N		B 2 Crossing Direction	N/A	
N/A	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A	

Is Button 1 APS or Non-APS? Yes B 1 VibroTact Arrow? Yes B 1 VibroTact Parallel to Xing? Yes B 1 VibroTact Contrast Yes B 1 Pilot Light? Yes B 1 Pilot Light Illumination?

No B 1 Verbal Walk Cycle?

**APS** Is Button 2 APS or Non-APS? N/A Yes N/A B 2 VibroTact Arrow? N/A Yes N/A B 2 VibroTact Parallel to Xing? N/A Yes N/A B 2 VibroTact Contrast N/A Yes N/A B 2 Pilot Light? N/A Yes N/A B 2 Pilot Light Illumination? N/A Yes N/A B 2 Verbal Walk Cycle? N/A N/A B 1 Verbal Message Audible? Yes N/A B 2 Verbal Message Audible? N/A Yes N/A B 2 Locator Tone? N/A

Yes B 1 Locator Tone? No B 1 Percussive Walk Cycle? No N/A B 2 Percussive Walk Cycle? Yes B 1 Extended Press Feature? Yes N/A B 2 Extended Press Feature?

**APS Compliance** 

Yes B 1 Tone Audible Range? Yes N/A B 2 Tone Audible Range?