cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



					s Street: N/A Location: N/A				
ADA ID: 41BA23AD0E5B	Signal Type	:One Push Button-Non APS	Overall C	ompliance: No	Severity Score:	BTN 1:N//	A BTN 2: N/A	No BTN:	N/A
Codes		Field Measurements/Component Compliance							
	1.2.4	Possible Solutions: Remove and	l Replace	Compliance Description		Data Compliance Description		Data	
	6	Clear Space.		Button Count	B	utton1 N/A	Distant to Additiona	al Button (in)	N/A
	1			Additional Button Present?		No	Additional Button II)	N/A
Illan II	1 41			N/A Signal Buttons Required?		N/A N/A	Additional Ped Pos	ts Required	N/A
SEED STORE	-			How Many Ped Street Xings?		N/A	Located In An Islan	d/Median?	N/A
A A A A A A A A A A A A A A A A A A A		Surveyor Notes: N/A		N/A B 1 Sign Present?		Yes N/A	B 2 Sign Present?		N/A
A				Yes B1 Sign Purpose?		B 2 Sign Purpose?		N/A	
A AND A AND			Yes B 1 Sign Lettering & Contrast?		Yes N/A	B 2 Sign Lettering	& Contrast?	N/A	
	12			Yes B 1 Parallel To XWalk?		Yes N/A	B 2 Parallel To XW	alk?	N/A
Real Real	the and	PROW/ADA: R404.2, R404.3, R4	404.2, R404.3, R404.7.3,		n?	Yes N/A	B 2 PAR to Button?	•	N/A
	R404.7.2		Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk?	•	N/A	
Total Cost: \$ 400.00 Image: Cost of the second se				Yes B 1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Spa	ace?	N/A
				N/A B1 FWD Approa	ich?	No N/A	B 2 FWD Approach	?	N/A
				0 N/A B 1 FWD Approa	ch Constrained?	N/A N/A	B 2 FWD Approach	Constrained?	N/A
				N/A B 1 FWD Approa	ich Reach (in)	N/A N/A	B 2 FWD Approach	i Reach (in)	N/A
				N/A B 1 FWD Approa	ich Width (in)	N/A N/A	B 2 FWD Approach	ı Width (in)	N/A
				N/A B 1 FWD Approa	ch Obstruction?	No N/A	B 2 FWD Approach	Obstruction?	N/A
				N/A B 1 FWD Approa	ch Obstruction Dist (in)	N/A N/A	B 2 FWD Approach	ObstructionDist	t (in) N/A
				N/A B 1 PARA Approa	ach?	Yes N/A	B 2 PARA Approac	h?	N/A
				N/A B 1 PARA Approa	ach Constrained?	Yes N/A	B 2 PARA Approac	h Constrained?	N/A
1877 Aug	No B 1 PARA Approa	ach Reach (in)	52.0 N/A	B 2 PARA Approac	h Reach (in)	N/A			
1	No B 1 PARA Approa	ach Width (in)	48.0 N/A	B 2 PARA Approac	h Width (in)	N/A			
	N/A B 1 PARA Approa	ach Obstruction?	No N/A	B 2 PARA Approac	h Obstruction?	N/A			
APS Compliance				N/A B 1 PARA Approa	ach Obstruction Dist (in)	N/A N/A	B 2 PARA Approac	h ObstructionDis	st (in) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B1 Clear Floor S	Space Slope (%)	N/A N/A	B 2 Clear Floor Spa	ace Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	No B1 Clear Floor S	Space XSlope (%)	N/A N/A	B 2 Clear Floor Spa	ace XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B1 PAR Slope (9	%)	N/A N/A	B 2 PAR Slope (%)		N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)		38.0 N/A	B 2 Height (in)		N/A
N/A B 1 Pilot Light?	N/A	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		2.0 N/A	B 2 Pressure (#)		N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist C	Operation?	Yes N/A	B 2 Closed Fist Op	eration?	N/A
N/A B 1 Verbal Walk Cycle?	N/A	N/A B 2 Verbal Walk Cycle?	N/A	MUTC		ITCD Compliance			
N/A B 1 Verbal Message Audible?	N/A	N/A B 2 Verbal Message Audible?	N/A	N/A B1 Clear Xing Di	irection?	Yes N/A	B 2 Clear Xing Dire	ection?	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	B 1 Crossing Dire	ection	Το Ν	B 2 Crossing Direc	tion	N/A
N/A B 1 Percussive Walk Cycle?	N/A	N/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo X	(Walk (in)	42.0 N/A	B 2 DistanceTo XW	/alk (in)	N/A
N/A B1 Extended Press Feature?	N/A	N/A B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo C	Curb (in)	33.0 N/A	B 2 DistanceTo Cu	rb (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in))	2.0 N/A	B 2 Diameter (in)		N/A