

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

9CDEDAAB2FD6

500.0

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

ADA ID: 4977B50029B4 Signal Type: One Push Button-APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

No B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

Yes B 1 Diameter (in)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Additional Button ID

No N/A B 2 Sign Lettering & Contrast?

N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes

N/A



Possible Solutions: Remove & Replace Replace APS Button With New APS Button. Remove and Replace Clear Space.

Surveyor Notes: TEXT HT 5/16

Is Button 2 APS or Non-APS?

PROW/ADA: R410.6, R404.2, R404.3, R406.2, R404.7.3, R209.1, MUTCD 4e.10

Total Cost:

Yes N/A B 2 VibroTact Arrow?

Yes N/A B 2 Locator Tone?

Yes N/A B 2 VibroTact Parallel to Xing? Yes N/A B 2 VibroTact Contrast Yes N/A B 2 Pilot Light?

Yes N/A B 2 Pilot Light Illumination? Yes N/A B 2 Verbal Walk Cycle? Yes N/A B 2 Verbal Message Audible?

Yes N/A B 2 Percussive Walk Cycle? Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?

1150.00 N/A B 1 FWD Approach Constrained?

N/A



APS Compliance APS



1150.00	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A
		B 1 FWD Approach Reach (in)			B 2 FWD Approach Reach (in)	N/A
- 1		B 1 FWD Approach Width (in)			B 2 FWD Approach Width (in)	N/A
A STATE OF THE STA		B 1 FWD Approach Obstruction?			B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction D			B 2 FWD Approach ObstructionDist (in)	N/A
		B 1 PARA Approach?	` '		B 2 PARA Approach?	N/A
		B 1 PARA Approach Constrained?			B 2 PARA Approach Constrained?	N/A
	No	B 1 PARA Approach Reach (in)	21.0	N/A	B 2 PARA Approach Reach (in)	N/A
	N/A	B 1 PARA Approach Width (in)			B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction [Dist (in) 8.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
N/A	No	B 1 Clear Floor Space Slope (%)	2.7	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A	No	B 1 Clear Floor Space XSlope (%	2.9	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A	N/A	B 1 PAR Slope (%)	0.0	N/A	B 2 PAR Slope (%)	N/A
N/A	Yes	B 1 Height (in)	43.0	N/A	B 2 Height (in)	N/A
N/A	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A
N/A	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A	MUTCD Compliance					
N/A	Yes	B 1 Clear Xing Direction?	learlyMarked	N/A	B 2 Clear Xing Direction?	N/A
N/A		B 1 Crossing Direction	То Е		B 2 Crossing Direction	N/A
N/A	Yes	B 1 DistanceTo XWalk (in)	10.0	N/A	B 2 DistanceTo XWalk (in)	N/A
N/A	Yes	B 1 DistanceTo Curb (in)	69.0	N/A	B 2 DistanceTo Curb (in)	N/A

	Is Button 1 APS or Non-APS?	
Yes	B 1 VibroTact Arrow?	
Yes	B 1 VibroTact Parallel to Xing?	
Yes	B 1 VibroTact Contrast	
Yes	B 1 Pilot Light?	
Yes	B 1 Pilot Light Illumination?	
No	B 1 Verbal Walk Cycle?	
N/A	B 1 Verbal Message Audible?	
Yes	B 1 Locator Tone?	
Yes	B 1 Percussive Walk Cycle?	
Yes	B 1 Extended Press Feature?	
Yes	B 1 Tone Audible Range?	