

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

F5FE8562395C

108.0

N/A

Yes

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-APS ADA ID: 49CA7512F89E **Overall Compliance: No** N/A

Compliance Description

Additional Button Present?

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

115.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

Distant to Additional Button (in)

Data

Button1 No

Yes



Yes B 1 Extended Press Feature?

Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA:, TMUTCD 4e.08, R404.2, R404.3, R406.2

Total Cost:

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?



N/A Signal Buttons Required? N/A N/A Additional Ped Posts Required Located In An Island/Median? How Many Ped Street Xings? N/A B 1 Sign Present? Yes N/A B 2 Sign Present? Yes N/A B 2 Sign Purpose? Yes B 1 Sign Purpose? Yes B 1 Sign Lettering & Contrast? Yes N/A B 2 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk? Yes N/A B 2 Parallel To XWalk? Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? Yes B 1 PAR to XWalk? Yes N/A B 2 PAR to XWalk? Yes N/A B 2 Clear Floor Space? Yes B 1 Clear Floor Space? N/A B 1 FWD Approach? Yes N/A B 2 FWD Approach? 650.00 N/A B 1 FWD Approach Constrained? **No N/A** B 2 FWD Approach Constrained? No B 1 FWD Approach Reach (in) 9.0 N/A B 2 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in) N/A B 1 FWD Approach Obstruction? Yes N/A B 2 FWD Approach Obstruction? N/A B 1 FWD Approach Obstruction Dist (in) 4.0 N/A B 2 FWD Approach ObstructionDist (in) Yes N/A B 2 PARA Approach? N/A B 1 PARA Approach? **N/A** B 1 PARA Approach Constrained? **No N/A** B 2 PARA Approach Constrained? Yes B 1 PARA Approach Reach (in) 9.0 N/A B 2 PARA Approach Reach (in)



			N/A B 1 PARA Approach Width (in)		A B 2 PARA Approach V	Vidth (in) N/A	
				N/A B 1 PARA Approach Obstruction	on? Yes N	A B 2 PARA Approach C	Obstruction? N/A
APS Compliance				N/A B 1 PARA Approach Obstruction Dist (in)		A B 2 PARA Approach C	ObstructionDist (in) N/A
Is Button 1 APS or Non-APS?	APS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope ((%) 5.8 N	A B 2 Clear Floor Space	e Slope (%) N/A
Yes B 1 VibroTact Arrow?	Yes N/	A B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope	e (%) 1.4 N	A B 2 Clear Floor Space	e XSlope (%) N/A
Yes B 1 VibroTact Parallel to Xing?	Yes N/	A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	2.8 N	A B 2 PAR Slope (%)	N/A
Yes B 1 VibroTact Contrast	Yes N/	A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	46.0 N	A B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes N/	A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0 N	A B 2 Pressure (#)	N/A
Yes B 1 Pilot Light Illumination?	Yes N/	A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N	A B 2 Closed Fist Opera	ation? N/A
Yes B 1 Verbal Walk Cycle?	Yes N/	A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance			
Yes B 1 Verbal Message Audible?	Yes N/	A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	ClearlyMarked N	A B 2 Clear Xing Directi	on? N/A
Yes B 1 Locator Tone?	Yes N/	A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To N	B 2 Crossing Direction	n N/A
No B 1 Percussive Walk Cycle?	Yes N/	A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0 N	A B 2 DistanceTo XWall	(in) N/A

N/A

N/A

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)