

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A N/A

Yes

Yes

Yes

Yes

Yes

Yes

Yes

Yes

No

N/A

N/A

Yes

3.0

2.0

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 4AA6FFEADF23

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

Yes B 1 Diameter (in)

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button2 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes Yes B 2 Sign Purpose?

Yes Yes B 2 Parallel To XWalk?

Yes Yes B 2 Clear Floor Space?

No N/A B 2 FWD Approach?

2.0 No B 2 Diameter (in)

Yes Yes B 2 PAR to Button?

Yes Yes B 2 PAR to XWalk?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes Yes B 2 Sign Lettering & Contrast?

N/A N/A B 2 FWD Approach Constrained?

N/A No B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Yes N/A B 2 FWD Approach Obstruction?

3.0 N/A B 2 FWD Approach Obstruction Dist (in)

Located In An Island/Median?

Data

N/A



N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: second button headed SW IS FOR BIKE ONLY

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R404.7.2, R406.2, R404.7.3, R406, R403.4

Total Cost:

N/A N/A B 2 Tone Audible Range?

1300.00 N/A B 1 FWD Approach Constrained?





	The state of the s			THE STATE OF THE S		THA BITT WB/Tpprodoil Obolidolloll Biol (III)	0.0	A BZ I WB Approudit Obstit		
						N/A B 1 PARA Approach?	Yes N	/A B 2 PARA Approach?	Yes	
	- y ann		A STATE OF THE STA		The state of the s	N/A B 1 PARA Approach Constrained?	Yes N	/A B 2 PARA Approach Cons	strained? No	
	070					Yes B 1 PARA Approach Reach (in)	10.0 N	o B 2 PARA Approach Reac	ch (in) N/A	
						No B 1 PARA Approach Width (in)	48.0 N	/A B 2 PARA Approach Width	n (in) N/A	
						N/A B 1 PARA Approach Obstruction?	Yes N	/A B 2 PARA Approach Obstr	ruction? Yes	
APS Compliance						N/A B 1 PARA Approach Obstruction Dist (in)	3.0 N	/A B 2 PARA Approach Obstr	ructionDist (in) 3.0	
	Is Button 1 APS or Non-APS?	NonAPS	Is Button 2	APS or Non-APS?	NonAPS	No B 1 Clear Floor Space Slope (%)	3.4 N	o B 2 Clear Floor Space Slo	ppe (%) N/A	
N/A	B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTa	act Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)	0.4 N	B 2 Clear Floor Space XS	Slope (%) N/A	
N/A	B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTa	ct Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	N/A N	/A B 2 PAR Slope (%)	N/A	
N/A	B 1 VibroTact Contrast	N/A	N/A B 2 VibroTa	act Contrast	N/A	Yes B 1 Height (in)	37.0 N	o B 2 Height (in)	37	
N/A	B 1 Pilot Light?	N/A	N/A B 2 Pilot Lig	ght?	N/A	Yes B 1 Pressure (#)	2.0 N	o B 2 Pressure (#)	N/A	
N/A	B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Lig	ght Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes Y	es B 2 Closed Fist Operation	? Yes	
N/A	B 1 Verbal Walk Cycle?	N/A	N/A B 2 Verbal \	Walk Cycle?	N/A	MUTCD Compliance				
N/A	B 1 Verbal Message Audible?	N/A	N/A B 2 Verbal N	Message Audible?	N/A	N/A B 1 Clear Xing Direction?	Yes N	/A B 2 Clear Xing Direction?	Yes	
N/A	B 1 Locator Tone?	N/A	N/A B 2 Locator	Tone?	N/A	B 1 Crossing Direction	To SE	B 2 Crossing Direction	To SW	
N/A	B 1 Percussive Walk Cycle?	N/A	N/A B 2 Percuss	sive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	10.0 N	B 2 DistanceTo XWalk (in)) N/A	
N/A	B 1 Extended Press Feature?	N/A	N/A B 2 Extende	ed Press Feature?	N/A	No B 1 DistanceTo Curb (in)	97.0 N	B 2 DistanceTo Curb (in)	N/A	

N/A