

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A

No

Yes

Yes

No

Yes

Yes

Yes

Yes

Yes

No

12.0

N/A

Yes

4.0

Yes

2.0

74.0

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 4AEAE6E83368

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

No B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

Button2 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes Yes B 2 Sign Purpose?

Yes Yes B 2 Parallel To XWalk?

Yes B 2 PAR to XWalk?

Yes Yes B 2 Clear Floor Space?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

74.0 No B 2 DistanceTo Curb (in)

2.0 Yes B 2 Diameter (in)

Yes Yes B 2 PAR to Button?

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

No B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

9.0 No B 2 FWD Approach Reach (in)

Yes N/A B 2 FWD Approach Obstruction?

**4.0** N/A B 2 FWD Approach ObstructionDist (in)

N/A N/A B 2 FWD Approach Width (in)

Data



N/A B 1 Tone Audible Range?

N/A B 1 Extended Press Feature?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 7/16

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R404.3, R406.2

Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

1400.00 N/A B 1 FWD Approach Constrained?





	Rec							
			A CONTRACTOR OF THE CONTRACTOR	N/A B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrain	ed? <b>No</b>
				Yes B 1 PARA Approach Reach (in)	7.0	Yes	B 2 PARA Approach Reach (in	9.0
		ascho, III		N/A B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction	on? Yes
APS Compliance				N/A B 1 PARA Approach Obstruction D	oist (in) 3.0	N/A	B 2 PARA Approach Obstruction	onDist (in) 3.5
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	NonAPS	No B 1 Clear Floor Space Slope (%)	5.2	No	B 2 Clear Floor Space Slope (	%) 9.1
N/A B 1 VibroTact Arrow?	N/A N/	A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	9.5	No	B 2 Clear Floor Space XSlope	(%) 5.8
N/A B 1 VibroTact Parallel to Xing?	N/A N/	A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	1.9	N/A	B 2 PAR Slope (%)	3.6
N/A B 1 VibroTact Contrast	N/A N/	A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	40.0	Yes	B 2 Height (in)	38.0
N/A B 1 Pilot Light?	N/A N/	A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0	Yes	B 2 Pressure (#)	2.0
N/A B 1 Pilot Light Illumination?	N/A N/	A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	Yes	B 2 Closed Fist Operation?	Yes
N/A B 1 Verbal Walk Cycle?	N/A N/	A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	N/A N/	A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	earlyMarked	Yes	B 2 Clear Xing Direction?	ClearlyMarked
N/A B 1 Locator Tone?	N/A N/	A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To SW		B 2 Crossing Direction	To S
N/A B 1 Percussive Walk Cycle?	N/A N/	A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	10.0	Yes	B 2 DistanceTo XWalk (in)	0.0

N/A

N/A