

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 4BF15EB6FBFA **Overall Compliance: No**

Button Count

N/A B 1 FWD Approach Obstruction?

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

N/A B 1 PARA Approach?

N/A B 1 FWD Approach Obstruction Dist (in)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 FWD Approach Obstruction?

No N/A B 2 PARA Approach Constrained?

N/A B 2 PARA Approach Reach (in)

Yes N/A B 2 PARA Approach?

96.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

2.0 N/A B 2 FWD Approach ObstructionDist (in)

Data



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Compliance Description Possible Solutions: Replace Signal Push Button With APS Button on New Post. Surveyor Notes: N/A PROW/ADA: R209.1, TMUTCD 4e.08, R404.2, R406.2

Additional Button Present? No Additional Button ID N/A Signal Buttons Required? N/A N/A Additional Ped Posts Required Located In An Island/Median? How Many Ped Street Xings? No B 1 Sign Present? No N/A B 2 Sign Present? N/A N/A B 2 Sign Purpose? N/A B 1 Sign Purpose? N/A B 1 Sign Lettering & Contrast? N/A N/A B 2 Sign Lettering & Contrast? N/A B 1 Parallel To XWalk? N/A B 2 Parallel To XWalk? Yes B 1 PAR to Button? N/A B 2 PAR to Button? Yes B 1 PAR to XWalk? N/A B 2 PAR to XWalk? Yes B 1 Clear Floor Space? Yes N/A B 2 Clear Floor Space? N/A B 1 FWD Approach? Yes N/A B 2 FWD Approach? 450.00 N/A B 1 FWD Approach Constrained? **No N/A** B 2 FWD Approach Constrained? No B 1 FWD Approach Reach (in) 9.0 N/A B 2 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in)



Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?



		The state of the s	- 15 d 1 d 1 d 1 d 1 d 1 d 1 d 1 d 1 d 1	N/A B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction	i? Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction	Dist (in) 2.0	N/A	B 2 PARA Approach ObstructionDist (in) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%	0.5	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%) 12. 6	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.2	N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	37.5	N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	ClearlyMarked	N/A	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	То Е	:	B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A

N/A

N/A