cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



((()									
Intersection ID: N/A	Main Street: Cross Street: N/A						Location: N/A		
ADA ID: 4D8E4307FF2B	Signal Type:Or	ne Push Button-Non APS	Overall Co	mpliance: No	Severity Score:	BTN 1:N//	A BTN 2: N/A	No BTN:	N/A
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
Possible Solutions: Replace Signal Push				Compliance Description		Data Compliance Description		Data	
Button With APS Button on New				Button Count	В	utton1 N/A	Distant to Addition	al Button (in)	N/A
Pril Plant	Remove & Relocate Sign.		Additional Button Present?		No Additional Button ID		D	N/A	
THE ATTACK				N/A Signal Buttons Required?		N/A N/A	Additional Ped Po	sts Required	N/A
ALL REAL PROVIDENCE				How Many Ped Street Xings?		N/A	Located In An Isla	nd/Median?	N/A
A COLORED IN		Surveyor Notes: N/A		N/A B 1 Sign Present?		Yes N/A	B 2 Sign Present?		N/A
				Yes B 1 Sign Purpose?		Yes N/A	B 2 Sign Purpose	?	N/A
	Ref. 1			Yes B1 Sign Lettering & Contrast?		Yes N/A	B 2 Sign Lettering	& Contrast?	N/A
				Yes B 1 Parallel To XWalk?		Yes N/A	B 2 Parallel To XW	/alk?	N/A
		PROW/ADA: TMUTCD 4e.08, R40	4.2, R404.3,	Yes B 1 PAR to Button?		Yes N/A	B 2 PAR to Button	?	N/A
the formation of the second		R404.7.3, R404.7.2		Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk	?	N/A
A Company	1 and the second			Yes B 1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Sp	bace?	N/A
- ALIAN				N/A B 1 FWD Approach?		No N/A	B 2 FWD Approac	h?	N/A
	14	Total Cost: \$	650.00	N/A B 1 FWD Approa	ach Constrained?	N/A N/A	B 2 FWD Approac	h Constrained?	N/A
				N/A B1 FWD Approa	ach Reach (in)	N/A N/A	B 2 FWD Approac	h Reach (in)	N/A
				N/A B1 FWD Approa	ach Width (in)	N/A N/A	B 2 FWD Approac	h Width (in)	N/A
				N/A B1 FWD Approa	ach Obstruction?	No N/A	B 2 FWD Approac	h Obstruction?	N/A
				N/A B 1 FWD Approa	ach Obstruction Dist (in)	N/A N/A	B 2 FWD Approac	h ObstructionDis	st (in) N/A
				N/A B 1 PARA Appro	ach?	Yes N/A	B 2 PARA Approa	ch?	N/A
				N/A B 1 PARA Approach Constrained?		Yes N/A B 2 PARA Approach Constrained?		N/A	
				No B 1 PARA Approach Reach (in)		30.0 N/A B 2 PARA Approach Reach (in)		N/A	
	No B 1 PARA Approach Width (in)		48.0 N/A	B 2 PARA Approa	ch Width (in)	N/A			
	N/A B 1 PARA Approach Obstruction?		No N/A	I/A B 2 PARA Approach Obstruction?		N/A			
	APS Complian	ce		N/A B 1 PARA Appro	ach Obstruction Dist (in)	N/A N/A	B 2 PARA Approa	ch ObstructionDi	st (in) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor S	Space Slope (%)	5.6 N/A	B 2 Clear Floor Sp	ace Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	Yes B1 Clear Floor S	Space XSlope (%)	0.7 N/A	B 2 Clear Floor Sp	ace XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope ((%)	N/A N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)		30.0 N/A	B 2 Height (in)		N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		2.0 N/A	B 2 Pressure (#)		N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B1 Closed Fist (Operation?	Yes N/A	B 2 Closed Fist O	peration?	N/A
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCI		UTCD Comp	CD Compliance		
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	N/A B1 Clear Xing D	Direction?	Yes N/A	B 2 Clear Xing Dir	ection?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Dir	ection	To NE	B 2 Crossing Dire	ction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo >	XWalk (in)	0.0 N/A	B 2 DistanceTo XV	Valk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	No B 1 DistanceTo 0	Curb (in)	89.0 N/A	B 2 DistanceTo Cu	urb (in)	N/A
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)	2.0 N/A	B 2 Diameter (in)		N/A