

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

CFA1EF843C37

344.0

N/A

No

N/A

N/A N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: 4F81E45570FB **Overall Compliance: No** N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space? N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

Yes B 1 DistanceTo XWalk (in)

Yes B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

N/A B 1 FWD Approach Obstruction Dist (in)

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

56.0 N/A B 2 DistanceTo XWalk (in)

58.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

No N/A B 2 FWD Approach Obstruction?

No N/A B 2 PARA Approach Constrained?

N/A B 2 PARA Approach Reach (in)

N/A N/A B 2 FWD Approach ObstructionDist (in)

0.0 N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Located In An Island/Median?

Data

Yes



N/A B 1 Percussive Walk Cycle?

N/A B 1 Tone Audible Range?

N/A B 1 Extended Press Feature?

Possible Solutions: Remove and Replace Clear Space.

Surveyor Notes: N/A

PROW/ADA: R404.2, R404.3

Total Cost:

N/A N/A B 2 Percussive Walk Cycle?

N/A N/A B 2 Tone Audible Range?

N/A N/A B 2 Extended Press Feature?





400.00 N/A B 1 FWD Approach Constrained?



| | . // | | | N/A B 1 PARA Approach Width (in) | N/A N | N/A | B 2 PARA Approach Width (in) | N/A |
|-------------------------------------|---------|-----------------------------------|-----|--|-----------------|-----|--|-----|
| | | | | N/A B 1 PARA Approach Obstruction? | No N | N/A | B 2 PARA Approach Obstruction? | N/A |
| APS Compliance | | | | N/A B 1 PARA Approach Obstruction Dist | (in) N/A | N/A | B 2 PARA Approach ObstructionDist (in) | N/A |
| Is Button 1 APS or Non-APS? | NonAPS | Is Button 2 APS or Non-APS? | N/A | No B 1 Clear Floor Space Slope (%) | 2.2 | N/A | B 2 Clear Floor Space Slope (%) | N/A |
| N/A B 1 VibroTact Arrow? | N/A N/A | A B 2 VibroTact Arrow? | N/A | No B 1 Clear Floor Space XSlope (%) | 2.3 | N/A | B 2 Clear Floor Space XSlope (%) | N/A |
| N/A B 1 VibroTact Parallel to Xing? | N/A N/A | A B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope (%) | 1.5 | N/A | B 2 PAR Slope (%) | N/A |
| N/A B 1 VibroTact Contrast | N/A N/A | A B 2 VibroTact Contrast | N/A | Yes B 1 Height (in) | 40.0 ا | N/A | B 2 Height (in) | N/A |
| N/A B 1 Pilot Light? | N/A N/A | A B 2 Pilot Light? | N/A | Yes B 1 Pressure (#) | 2.0 | N/A | B 2 Pressure (#) | N/A |
| N/A B 1 Pilot Light Illumination? | N/A N/A | A B 2 Pilot Light Illumination? | N/A | Yes B 1 Closed Fist Operation? | Yes | N/A | B 2 Closed Fist Operation? | N/A |
| N/A B 1 Verbal Walk Cycle? | N/A N/A | A B 2 Verbal Walk Cycle? | N/A | MUTCD Compliance | | | | |
| N/A B 1 Verbal Message Audible? | N/A N/A | A B 2 Verbal Message Audible? | N/A | Yes B 1 Clear Xing Direction? Clear | rlyMarked 1 | N/A | B 2 Clear Xing Direction? | N/A |
| N/A B 1 Locator Tone? | N/A N/A | A B 2 Locator Tone? | N/A | B 1 Crossing Direction | To NW | | B 2 Crossing Direction | N/A |

N/A

N/A

N/A