

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

81EF5E145F67

318.0

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 50C295F224D6 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

132.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes

N/A



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R404.7.2

Total Cost:

650.00

N/A

N/A

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)





	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?	N/A
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWD Approach?	N/A
)	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	5.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
	N/A	B 1 PARA Approach Constrained?	Yes	N/A	B 2 PARA Approach Constrained?	N/A
	Yes	B 1 PARA Approach Reach (in)	6.0	N/A	B 2 PARA Approach Reach (in)	N/A
	No	B 1 PARA Approach Width (in)	48.0	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)	6.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	No	B 1 Clear Floor Space Slope (%)	5.4	N/A	B 2 Clear Floor Space Slope (%)	N/A
	No	B 1 Clear Floor Space XSlope (%)	3.7	N/A	B 2 Clear Floor Space XSlope (%)	N/A
	N/A	B 1 PAR Slope (%)	N/A	N/A	B 2 PAR Slope (%)	N/A
	Yes	B 1 Height (in)	36.0	N/A	B 2 Height (in)	N/A
	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
		M	MUTCD Compliance			
	N/A	B 1 Clear Xing Direction?	Yes	N/A	B 2 Clear Xing Direction?	N/A
		B 1 Crossing Direction	To SW		B 2 Crossing Direction	N/A
	Yes	B 1 DistanceTo XWalk (in)	6.0	N/A	B 2 DistanceTo XWalk (in)	N/A

	Is Button 1 APS or Non-APS?			
N/A	B 1 VibroTact Arrow?			
N/A	B 1 VibroTact Parallel to Xing?			
N/A	B 1 VibroTact Contrast			
N/A	B 1 Pilot Light?			
N/A	B 1 Pilot Light Illumination?			
N/A	B 1 Verbal Walk Cycle?			
N/A	B 1 Verbal Message Audible?			
N/A	B 1 Locator Tone?			
N/A	B 1 Percussive Walk Cycle?			
N/A	B 1 Extended Press Feature?			

N/A B 1 Tone Audible Range?

APS Compliance							
NonAPS	PS Is Button 2 APS or Non-APS?		N/A				
N/A	N/A	B 2 VibroTact Arrow?	N/A				
N/A	N/A	B 2 VibroTact Parallel to Xing?	N/A				
N/A	N/A	B 2 VibroTact Contrast	N/A				
N/A	N/A	B 2 Pilot Light?	N/A				
N/A	N/A	B 2 Pilot Light Illumination?	N/A				
N/A	N/A	B 2 Verbal Walk Cycle?	N/A				
N/A	N/A	B 2 Verbal Message Audible?	N/A				
N/A	N/A	B 2 Locator Tone?	N/A				
N/A	N/A	B 2 Percussive Walk Cycle?	N/A				

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?