

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

37DEDCA49A0A

370.0

N/A N/A

N/A

N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-Non APS ADA ID: 590363A17A86 **Overall Compliance: No** N/A

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 Yes** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

132.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

Yes

N/A



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A


PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R404.7.2

Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?





B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

NIA
pproach Obstruction? N/A
proach ObstructionDist (in) N/A
oor Space Slope (%) N/A
oor Space XSlope (%) N/A
pe (%) N/A
n) <b>N/A</b>
e (#) N/A
Fist Operation? N/A
ng Direction? N/A
Direction N/A
To XWalk (in) N/A
ii

N/A

N/A