

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

Signal Type: ADA ID: 597375FB8579 **Overall Compliance: Yes** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button0 N/A Distant to Additional Button (in)

N/A N/A B 2 Sign Present?

N/A N/A B 2 Sign Purpose?

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

N/A B 2 Sign Lettering & Contrast?

N/A N/A B 2 FWD Approach Constrained?

N/A N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

N/A N/A B 2 FWD Approach Obstruction?

N/A N/A B 2 FWD Approach ObstructionDist (in)


N/A B 2 Parallel To XWalk?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?


N/A N/A B 2 Clear Floor Space? N/A N/A B 2 FWD Approach?

Data



Possible Solutions: N/A Surveyor Notes: N/A PROW/ADA: N/A

N/A B 1 Sign Purpose? N/A B 1 Sign Lettering & Contrast? N/A B 1 Parallel To XWalk? N/A B 1 PAR to Button? N/A B 1 PAR to XWalk? N/A B 1 Clear Floor Space?



Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

N/A B 1 Sign Present?

