Cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



| Intersection ID: N/A | Main Street: Cross Street: N/A | | | | | | Location: N/A | | |
|---|--------------------------------|---|---|---|------------------------------------|------------------------------|--------------------------------------|-----------------|--------------------|
| ADA ID: 5E9DE5488914 | Signal Type:O | ne Push Button-Non APS | Overall Co | mpliance: No | Severity Score: E | BTN 1:N/A | A BTN 2: N/A | No BTN: | N/A |
| Code | s/Mitigation Info | | Field Measurements/Component Compliance | | | | | | |
| | | Possible Solutions: Replace Signa Button With APS Button on New Po | nal Buah | Compliance Description | | Data Compliance Description | | | Data |
| | The second second | | Post. | Button Count | Bu | itton1 N/A | Distant to Addition | al Button (in) | N/A |
| | | Remove & Replace Sign. | | Additional Button Present? | | No | Additional Button I | D | N/A |
| | | | | N/A Signal Buttons Required? | | N/A N/A | Additional Ped Pos | sts Required | N/A |
| | 5 · 来的,自己的 | | | How Many Ped Street Xings? | | 2 | Located In An Isla | nd/Median? | No |
| AND | ۥ | Surveyor Notes: TEXT HT 7/16 | | N/A B 1 Sign Present? | | Yes N/A | B 2 Sign Present? | | N/A |
| SP - | CONTRACT OF | | | Yes B 1 Sign Purpose? | | Yes N/A | B 2 Sign Purpose? | • | N/A |
| | 11 | | | No B 1 Sign Lettering & Contrast? | | No N/A | B 2 Sign Lettering | & Contrast? | N/A |
| | | | | Yes B 1 Parallel To XWalk? | | Yes N/A B 2 Parallel To XWal | | /alk? | N/A |
| | | PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R404.3, R406.2, R404.7.3 | | Yes B 1 PAR to Button? | | Yes N/A | B 2 PAR to Button | ? | N/A |
| - 77 | 1 Carlos | | | Yes B 1 PAR to XWalk? | | Yes N/A | B 2 PAR to XWalk | ? | N/A |
| 115 | to man | | | Yes B1 Clear Floor Space? | | Yes N/A | B 2 Clear Floor Sp | ace? | N/A |
| 1 Same | 100 - 2 3.0 | | | N/A B1 FWD Approach? | | Yes N/A | B 2 FWD Approac | h? | N/A |
| | 100 / 17 martin | Total Cost: \$ | 700.00 | N/A B 1 FWD Approa | ch Constrained? | No N/A | B 2 FWD Approac | h Constrained? | N/A |
| | | No B 1 FWD Approa | ch Reach (in) | 37.0 N/A | B 2 FWD Approac | h Reach (in) | N/A | | |
| | | | | N/A B1 FWD Approach Width (in) | | N/A N/A | B 2 FWD Approac | h Width (in) | N/A |
| | | | | N/A B 1 FWD Approach Obstruction? | | Yes N/A | B 2 FWD Approac | h Obstruction? | N/A |
| | | | | N/A B 1 FWD Approach Obstruction Dist (in | | 8.5 N/A | N/A B 2 FWD Approach ObstructionDist | | st (in) N/A |
| | | | | N/A B 1 PARA Approach? | | Yes N/A | N/A B 2 PARA Approach? | | N/A |
| | | | | N/A B 1 PARA Approach Constrained? | | No N/A | N/A B 2 PARA Approach Constrained? | | N/A |
| | | No B 1 PARA Approach Reach (in) | | 30.0 N/A | N/A B 2 PARA Approach Reach (in) | | N/A | | |
| | | | | N/A B 1 PARA Approach Width (in) | | N/A N/A | B 2 PARA Approac | h Width (in) | N/A |
| | | N/A B 1 PARA Approach Obstruction? | | Yes N/A | N/A B 2 PARA Approach Obstruction? | | N/A | | |
| | APS Compliar | nce | | N/A B 1 PARA Approa | ach Obstruction Dist (in) | 6.5 N/A | B 2 PARA Approac | h ObstructionDi | st (in) N/A |
| Is Button 1 APS or Non-APS? | NonAPS | Is Button 2 APS or Non-APS? | N/A | No B1 Clear Floor S | Space Slope (%) | 3.0 N/A | B 2 Clear Floor Sp | ace Slope (%) | N/A |
| N/A B 1 VibroTact Arrow? | N/A N/A | B 2 VibroTact Arrow? | N/A | No B1 Clear Floor S | Space XSlope (%) | 2.3 N/A | B 2 Clear Floor Sp | ace XSlope (%) | N/A |
| N/A B1 VibroTact Parallel to Xing? | N/A N/A | B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope (% | %) | 0.2 N/A | B 2 PAR Slope (% |) | N/A |
| N/A B 1 VibroTact Contrast | N/A N/A | B 2 VibroTact Contrast | N/A | Yes B 1 Height (in) | | 40.0 N/A | B 2 Height (in) | | N/A |
| N/A B 1 Pilot Light? | N/A N/A | B 2 Pilot Light? | N/A | Yes B 1 Pressure (#) | | 2.0 N/A | B 2 Pressure (#) | | N/A |
| N/A B 1 Pilot Light Illumination? | N/A N/A | B 2 Pilot Light Illumination? | N/A | Yes B 1 Closed Fist C | Operation? | Yes N/A | B 2 Closed Fist Op | peration? | N/A |
| N/A B 1 Verbal Walk Cycle? | N/A N/A | B 2 Verbal Walk Cycle? N/A | | N | | MUTCD Compliance | | | |
| N/A B 1 Verbal Message Audible? | N/A N/A | B 2 Verbal Message Audible? | N/A | Yes B 1 Clear Xing Di | irection? ClearlyM | arked N/A | B 2 Clear Xing Dire | ection? | N/A |
| N/A B 1 Locator Tone? | N/A N/A | B 2 Locator Tone? | N/A | B 1 Crossing Dire | ection | To NE | B 2 Crossing Direc | tion | N/A |
| N/A B 1 Percussive Walk Cycle? | N/A N/A | B 2 Percussive Walk Cycle? | N/A | No B 1 DistanceTo X | Walk (in) | 92.0 N/A | B 2 DistanceTo XV | Valk (in) | N/A |
| N/A B 1 Extended Press Feature? | N/A N/A | B 2 Extended Press Feature? | N/A | No B 1 DistanceTo C | Curb (in) | 154.0 N/A | B 2 DistanceTo Cu | ırb (in) | N/A |
| N/A B 1 Tone Audible Range? | N/A N/A | B 2 Tone Audible Range? | N/A | Yes B 1 Diameter (in) | | 2.0 N/A | B 2 Diameter (in) | | N/A |