

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

N/A

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A **ADA ID: 6167BB9F26DC**

Compliance Description

Additional Button Present?

Yes B 1 DistanceTo XWalk (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Compliance Description

Button1 N/A Distant to Additional Button (in)

0.0 N/A B 2 DistanceTo XWalk (in)

105.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

Data



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R406.2

Total Cost:

650.00

N/A

N/A



No N/A B 2 Extended Press Feature?

No N/A B 2 Tone Audible Range?



		Additional Button Fresent?	NO		Additional Button ID	IV/A				
	N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required	N/A				
		How Many Ped Street Xings?	2		Located In An Island/Median?	No				
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	N/A				
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A				
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?	N/A				
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A				
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A				
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A				
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A				
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A				
)	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A				
	No	B 1 FWD Approach Reach (in)	8.0	N/A	B 2 FWD Approach Reach (in)	N/A				
	N/A	B 1 FWD Approach Width (in)	60.0	N/A	B 2 FWD Approach Width (in)	N/A				
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A				
	N/A	B 1 FWD Approach Obstruction Dist (in)	6.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A				
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A				
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A				
	Yes	B 1 PARA Approach Reach (in)	8.0	N/A	B 2 PARA Approach Reach (in)	N/A				
	N/A	B 1 PARA Approach Width (in)	60.0	N/A	B 2 PARA Approach Width (in)	N/A				
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A				
	N/A	B 1 PARA Approach Obstruction Dist (in)	6.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A				
	No	B 1 Clear Floor Space Slope (%)	5.1	N/A	B 2 Clear Floor Space Slope (%)	N/A				
	Yes	B 1 Clear Floor Space XSlope (%)	0.3	N/A	B 2 Clear Floor Space XSlope (%)	N/A				
	N/A	B 1 PAR Slope (%)	3.1	N/A	B 2 PAR Slope (%)	N/A				
	Yes	B 1 Height (in)	38.0	N/A	B 2 Height (in)	N/A				
	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A				
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A				
MUTCD Compliance										
	Yes	B 1 Clear Xing Direction? ClearlyMa	arked	N/A	B 2 Clear Xing Direction?	N/A				
		B 1 Crossing Direction	To W		B 2 Crossing Direction	N/A				

APS Compliance									
ls l	Button 1 APS or Non-APS? No n	APS	ls l	Button 2 APS or Non-APS?	N/A				
N/A B	1 VibroTact Arrow?	No N/	A B 2	2 VibroTact Arrow?	N/A				
N/A B 1	l VibroTact Parallel to Xing?	No N/	A B 2	2 VibroTact Parallel to Xing?	N/A				
N/A B	1 VibroTact Contrast	No N/	A B 2	2 VibroTact Contrast	N/A				
N/A B	1 Pilot Light?	No N/	A B 2	2 Pilot Light?	N/A				
N/A B1	Pilot Light Illumination?	No N/	A B 2	2 Pilot Light Illumination?	N/A				
N/A B 1	1 Verbal Walk Cycle?	No N/	A B 2	2 Verbal Walk Cycle?	N/A				
N/A B 1	1 Verbal Message Audible?	No N/	A B 2	2 Verbal Message Audible?	N/A				
N/A B	1 Locator Tone?	No N/	A B 2	2 Locator Tone?	N/A				
N/A B1	Percussive Walk Cycle?	No N/	A B 2	Percussive Walk Cycle?	N/A				