## cole

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Intersection ID: N/A	Main Street: Cross Street: N/A						Location: N/A		
ADA ID: 667D5DF3FFEB	Signal Type: Two	Push Buttons-Non APS	Overall Co	mpliance: No	Severity Score: B	TN 1:N/	A BTN 2: N/A	No BTN:	N/A
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
Dessible Salutional Dravide Duck Putter				Compliance Descri	ption D	ata Con	npliance Descripti	on	Data
	and the second s	Possible Solutions: Provide Push Butte Extension. Remove and Replace Clear		Button Count	But	ton2 N/A	Distant to Addition	al Button (in)	N/A
				Additional Button	Present?	No	Additional Button I	D	N/A
				N/A Signal Buttons Re	equired?	N/A N/A	Additional Ped Pos	sts Required	N/A
				How Many Ped S	treet Xings?	2	Located In An Islar	nd/Median?	No
	Sector Sector	Surveyor Notes: N/A		N/A B 1 Sign Present	?	Yes N/A	B 2 Sign Present?		Yes
				Yes B 1 Sign Purpose	?	Yes Yes	B 2 Sign Purpose?	,	Yes
					es B 1 Sign Lettering & Contrast?		B 2 Sign Lettering	& Contrast?	Yes
I TILL & TILL &	DA Dis	PROW/ADA: R404.2, R404.3, R406.2		Yes B 1 Parallel To XWalk?		Yes Yes	B 2 Parallel To XW	′alk?	Yes
Gue	SU TONT			Yes B 1 PAR to Button?		Yes Yes	B 2 PAR to Button	?	Yes
1	E. FFFF			Yes B 1 PAR to XWall	k?	Yes Yes	B 2 PAR to XWalk	?	Yes
HT I AL	Sur E			Yes B1 Clear Floor S	pace?	Yes Yes	B 2 Clear Floor Sp	ace?	Yes
	E - E			N/A B 1 FWD Approac		Yes N/A	B 2 FWD Approacl	ר?	Yes
	🌅 🤐 🚟 🕌 То	tal Cost: \$	1800.00	N/A B 1 FWD Approac	ch Constrained?	No N/A	B 2 FWD Approacl	n Constrained?	No
				No B 1 FWD Approac	ch Reach (in)		B 2 FWD Approacl		9.0
				N/A B 1 FWD Approac	ch Width (in)	N/A N/A	B 2 FWD Approacl	n Width (in)	N/A
				N/A B 1 FWD Approac	ch Obstruction?	Yes N/A	B 2 FWD Approacl	n Obstruction?	Yes
				N/A B 1 FWD Approac	ch Obstruction Dist (in)	0.0 N/A	B 2 FWD Approacl	n ObstructionDis	st (in) 3.0
				N/A B 1 PARA Approa	ach?	Yes N/A	B 2 PARA Approac	h?	Yes
				N/A B 1 PARA Approach Constrained?		No N/A	B 2 PARA Approac	h Constrained?	No
				Yes B 1 PARA Approach Reach (in)		5.0 Yes	B 2 PARA Approac	h Reach (in)	5.0
				N/A B 1 PARA Approach Width (in)			B 2 PARA Approac		N/A
				N/A B 1 PARA Approa			B 2 PARA Approac		Yes
	APS Compliance				ach Obstruction Dist (in)		B 2 PARA Approac		
Is Button 1 APS or Non-APS?		Button 2 APS or Non-APS?	NonAPS	No B 1 Clear Floor S	,		B 2 Clear Floor Sp		2.6
N/A B 1 VibroTact Arrow?		2 VibroTact Arrow?	N/A	No B 1 Clear Floor S	,		B 2 Clear Floor Sp		
N/A B 1 VibroTact Parallel to Xing?		2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%	%)		B 2 PAR Slope (%	)	2.4
N/A B 1 VibroTact Contrast		2 VibroTact Contrast	N/A	Yes B 1 Height (in)			B 2 Height (in)		43.0
N/A B 1 Pilot Light?		2 Pilot Light?	N/A	Yes B 1 Pressure (#)			B 2 Pressure (#)		3.0
N/A B 1 Pilot Light Illumination?		2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist C		•	B 2 Closed Fist Op	eration?	Yes
N/A B 1 Verbal Walk Cycle?			MUTCD Compliance   Yes B 1 Clear Xing Direction? ClearlyMarked Yes B 2 Clear Xing Direction? ClearlyMarked						
N/A B 1 Verbal Message Audible? N/A B 1 Locator Tone?		•	N/A	•	-		-		
		2 Locator Tone?	N/A	B 1 Crossing Dire		SW Noc	B 2 Crossing Direc		To S
N/A B 1 Percussive Walk Cycle? N/A B 1 Extended Press Feature?		2 Percussive Walk Cycle? 2 Extended Press Feature?	N/A N/A	Yes B 1 DistanceTo X Yes B 1 DistanceTo C	. ,		B 2 DistanceTo XV B 2 DistanceTo Cu		0.0 71.0
N/A B 1 Tone Audible Range?		2 Tone Audible Range?	N/A N/A	Yes B 1 Distance to C			B 2 Distance to Cu B 2 Diameter (in)		2.0
									2.0