
		Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.	
		Surveyor Notes: N/A	
		PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R404.7.3	
		Total Cost: \$ 650.00	
			
APS Compliance		MUTCD Compliance	
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A
N/A B 1 VibroTact Arrow?	No	N/A B 2 VibroTact Arrow?	N/A
N/A B 1 VibroTact Parallel to Xing?	No	N/A B 2 VibroTact Parallel to Xing?	N/A
N/A B 1 VibroTact Contrast	No	N/A B 2 VibroTact Contrast	N/A
N/A B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A
N/A B 1 Pilot Light Illumination?	No	N/A B 2 Pilot Light Illumination?	N/A
N/A B 1 Verbal Walk Cycle?	No	N/A B 2 Verbal Walk Cycle?	N/A
N/A B 1 Verbal Message Audible?	No	N/A B 2 Verbal Message Audible?	N/A
N/A B 1 Locator Tone?	No	N/A B 2 Locator Tone?	N/A
N/A B 1 Percussive Walk Cycle?	No	N/A B 2 Percussive Walk Cycle?	N/A
N/A B 1 Extended Press Feature?	No	N/A B 2 Extended Press Feature?	N/A
N/A B 1 Tone Audible Range?	No	N/A B 2 Tone Audible Range?	N/A
MUTCD Compliance		MUTCD Compliance	
Yes B 1 Clear Xing Direction?	ClearlyMarked	N/A B 2 Clear Xing Direction?	N/A
B 1 Crossing Direction	To NW	B 2 Crossing Direction	N/A
Yes B 1 DistanceTo XWalk (in)	15.0	N/A B 2 DistanceTo XWalk (in)	N/A
No B 1 DistanceTo Curb (in)	77.0	N/A B 2 DistanceTo Curb (in)	N/A
Yes B 1 Diameter (in)	2.0	N/A B 2 Diameter (in)	N/A