

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

ACBCE0531F11

379.0

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 6E0B8D3EDCDD Signal Type: One Push Button-APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

Additional Button Present?

How Many Ped Street Xings?

N/A Signal Buttons Required?

**Button Count** 

N/A B 1 Sign Present?

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

**Compliance Description** 

**Button1** Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes

N/A



Possible Solutions: Remove & Replace Replace APS Button With New APS Button. Remove and Replace Clear Space.

Surveyor Notes: STILL NOT HOOKED UP, NOISES, VERBAL NOTICES UNKNOWN

PROW/ADA: R404.2, R404.7.3, R404.7.2, MUTCD 4e.08, R104.2, R209.1,

Total Cost:

\$ 1150.00

N/A N/A N/A N/A N/A N/A N/A N/A





	11//	D 1 Olgit i teschi:	103	11//	D Z Olgit i resent:	11//		
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A		
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?	N/A		
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A		
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A		
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A		
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A		
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWD Approach?	N/A		
0	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A		
ŀ	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A		
į	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A		
Y	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A		
	N/A	B 1 FWD Approach Obstruction Dist (in)	4.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A		
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A		
	N/A	B 1 PARA Approach Constrained?	Yes	N/A	B 2 PARA Approach Constrained?	N/A		
1	No	B 1 PARA Approach Reach (in)	11.0	N/A	B 2 PARA Approach Reach (in)	N/A		
	No	B 1 PARA Approach Width (in)	48.0	N/A	B 2 PARA Approach Width (in)	N/A		
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A		
	N/A	B 1 PARA Approach Obstruction Dist (in)	4.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A		
		B 1 Clear Floor Space Slope (%)	0.2	N/A	B 2 Clear Floor Space Slope (%)	N/A		
	No	B 1 Clear Floor Space XSlope (%)	2.7	N/A	B 2 Clear Floor Space XSlope (%)	N/A		
	N/A	B 1 PAR Slope (%)	N/A	N/A	B 2 PAR Slope (%)	N/A		
	Yes	B 1 Height (in)	39.0	N/A	B 2 Height (in)	N/A		
	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A		
	Yes	B 1 Closed Fist Operation?	•	,	B 2 Closed Fist Operation?	N/A		
MUTCD Compliance								
	N/A	B 1 Clear Xing Direction?			B 2 Clear Xing Direction?	N/A		
		B 1 Crossing Direction	To NW		B 2 Crossing Direction	N/A		
	Yes	B 1 DistanceTo XWalk (in)			B 2 DistanceTo XWalk (in)	N/A		
	Yes	B 1 DistanceTo Curb (in)			B 2 DistanceTo Curb (in)	N/A		
	Yes	B 1 Diameter (in)	2.0	N/A	B 2 Diameter (in)	N/A		

APS Compliance									
	Is Button 1 APS or Non-APS?	APS		Is Button 2 APS or Non-APS?					
Yes	B 1 VibroTact Arrow?	Yes	N/A	B 2 VibroTact Arrow?					
Yes	B 1 VibroTact Parallel to Xing?	Yes	N/A	B 2 VibroTact Parallel to Xing?					
Yes	B 1 VibroTact Contrast	Yes	N/A	B 2 VibroTact Contrast					
No	B 1 Pilot Light?	N/A	N/A	B 2 Pilot Light?					
N/A	B 1 Pilot Light Illumination?	N/A	N/A	B 2 Pilot Light Illumination?					
N/A	B 1 Verbal Walk Cycle?	N/A	N/A	B 2 Verbal Walk Cycle?					
N/A	B 1 Verbal Message Audible?	N/A	N/A	B 2 Verbal Message Audible?					
No	B 1 Locator Tone?	N/A	N/A	B 2 Locator Tone?					
N/A	B 1 Percussive Walk Cycle?	N/A	N/A	B 2 Percussive Walk Cycle?					
No	B 1 Extended Press Feature?	N/A	N/A	B 2 Extended Press Feature?					
No	B 1 Tone Audible Range?	N/A	N/A	B 2 Tone Audible Range?					