

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 6F71FA9DE59D Signal Type: One Push Button-APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

No



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.7.3, R209.1, MUTCD 4e.10

Total Cost:

Yes N/A B 2 VibroTact Arrow?

Yes N/A B 2 VibroTact Contrast

Yes N/A B 2 Pilot Light Illumination?

Yes N/A B 2 Verbal Message Audible?

Yes N/A B 2 Percussive Walk Cycle?

Yes N/A B 2 Tone Audible Range?

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Verbal Walk Cycle?

Yes N/A B 2 Locator Tone?

Yes N/A B 2 Pilot Light?

Yes N/A B 2 VibroTact Parallel to Xing?

APS Compliance

650.00

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

Yes B 1 Diameter (in)



Is Button 2 APS or Non-APS?



	Yes	B 1 Clear Floor Space?	Yes N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	No N/A	B 2 FWD Approach?	N/A
.00	N/A	B 1 FWD Approach Constrained?	N/A N/A	B 2 FWD Approach Constrained?	N/A
14	N/A	B 1 FWD Approach Reach (in)	N/A N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	N/A N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A N/A	B 2 FWD Approach ObstructionDist (in)	N/A
1	N/A	B 1 PARA Approach?	Yes N/A	B 2 PARA Approach?	N/A
400	N/A	B 1 PARA Approach Constrained?	No N/A	B 2 PARA Approach Constrained?	N/A
	No	B 1 PARA Approach Reach (in)	21.0 N/A	B 2 PARA Approach Reach (in)	N/A
	N/A	B 1 PARA Approach Width (in)	N/A N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	No N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)	N/A N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Yes	B 1 Clear Floor Space Slope (%)	2.2 N/A	B 2 Clear Floor Space Slope (%)	N/A
	No	B 1 Clear Floor Space XSlope (%)	3.4 N/A	B 2 Clear Floor Space XSlope (%)	N/A
	N/A	B 1 PAR Slope (%)	2.3 N/A	B 2 PAR Slope (%)	N/A
	Yes	B 1 Height (in)	37.0 N/A	B 2 Height (in)	N/A
	Yes	B 1 Pressure (#)	3.0 N/A	B 2 Pressure (#)	N/A
	Yes	B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A
MUTCD Compliance					
	Yes	B 1 Clear Xing Direction? ClearlyMa	arked N/A	B 2 Clear Xing Direction?	N/A
		B 1 Crossing Direction	Го SE	B 2 Crossing Direction	N/A
	Yes	B 1 DistanceTo XWalk (in)	0.0 N/A	B 2 DistanceTo XWalk (in)	N/A
	No	B 1 DistanceTo Curb (in)	90.0 N/A	B 2 DistanceTo Curb (in)	N/A

Is Button 1 APS or Non-APS?
Yes B 1 VibroTact Arrow?
Yes B 1 VibroTact Parallel to Xing?
Yes B 1 VibroTact Contrast
Yes B 1 Pilot Light?
Yes B 1 Pilot Light Illumination?
No B 1 Verbal Walk Cycle?
N/A B 1 Verbal Message Audible?
Yes B 1 Locator Tone?
Yes B 1 Percussive Walk Cycle?
Yes B 1 Extended Press Feature?
Yes B 1 Tone Audible Range?