

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

No N/A

N/A N/A

Yes

Yes

Yes

Yes

0.0

2.0

78.0

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

ADA ID: 6FFDD1EBD734 Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

No B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

No B 1 Clear Floor Space?

Yes B 1 DistanceTo XWalk (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button2 N/A Distant to Additional Button (in)

Yes No B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

No Yes B 2 Clear Floor Space?

0.0 Yes B 2 DistanceTo XWalk (in)

80.0 No B 2 DistanceTo Curb (in)

2.0 Yes B 2 Diameter (in)

Yes Yes B 2 PAR to Button?

Yes Yes B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Additional Button ID

N/A N/A Additional Ped Posts Required

No N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

N/A



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 1/2

N/A N/A B 2 Tone Audible Range?

PROW/ADA: R410.6, TMUTCD 4e.08, R404.1, R406.2, R209.1, R404.2, R404.3

Total Cost:

1150.00





NonAPS

N/A

.00	N/A	B 1	FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	No
	No	B 1	FWD Approach Reach (in)	52.0	No	B 2 FWD Approach Reach (in)	8.0
	N/A	B 1	FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1	FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	Yes
	N/A	B 1	FWD Approach Obstruction Dist (in)	2.0	N/A	B 2 FWD Approach ObstructionDist (in)	2.0
	N/A	B 1	PARA Approach?	No	N/A	B 2 PARA Approach?	Yes
	N/A	B 1	PARA Approach Constrained?	N/A	N/A	B 2 PARA Approach Constrained?	No
	N/A	B 1	PARA Approach Reach (in)	N/A	Yes	B 2 PARA Approach Reach (in)	8.0
	N/A	B 1	PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	В 1	PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?	Yes
	N/A	B 1	PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach ObstructionDist (in)	2.0
	N/A	B 1	Clear Floor Space Slope (%)	N/A	No	B 2 Clear Floor Space Slope (%)	4.8
	N/A	B 1	Clear Floor Space XSlope (%)	N/A	No	B 2 Clear Floor Space XSlope (%)	10.1
	N/A	B 1	PAR Slope (%)	1.5	N/A	B 2 PAR Slope (%)	3.8
	Yes	B 1	Height (in)	40.0	Yes	B 2 Height (in)	39.2
	Yes	B 1	Pressure (#)	2.0	Yes	B 2 Pressure (#)	2.0
	Yes	B 1	Closed Fist Operation?	Yes	Yes	B 2 Closed Fist Operation?	Yes
	MUTCD Compliance						
	Yes	B 1	Clear Xing Direction? ClearlyMa	arked	No	B 2 Clear Xing Direction? NotClearlyMa	rked
		B 1	Crossing Direction	To S		B 2 Crossing Direction	o NE

	APS Compliance					
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?				
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?				
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	A B 2 VibroTact Parallel to Xing?				
N/A B 1 VibroTact Contrast	N/A N/A	A B 2 VibroTact Contrast				
N/A B 1 Pilot Light?	N/A N/A	A B 2 Pilot Light?				
N/A B 1 Pilot Light Illumination?	N/A N/A	A B 2 Pilot Light Illumination?				
N/A B 1 Verbal Walk Cycle?	N/A N/A	A B 2 Verbal Walk Cycle?				
N/A B 1 Verbal Message Audible?	N/A N/A	A B 2 Verbal Message Audible?				
N/A B 1 Locator Tone?	N/A N/A	A B 2 Locator Tone?				
N/A B 1 Percussive Walk Cycle?	N/A N/A	A B 2 Percussive Walk Cycle?				
N/A B 1 Extended Press Feature?	N/A N/A	A B 2 Extended Press Feature?				

N/A B 1 Tone Audible Range?