

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 763E521E746C Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

No B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?
N/A B 1 FWD Approach?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

2.0 N/A B 2 Diameter (in)

No N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

7.0 N/A B 2 FWD Approach Reach (in)

Yes N/A B 2 FWD Approach Obstruction?

5.0 N/A B 2 FWD Approach ObstructionDist (in)

60.0 N/A B 2 FWD Approach Width (in)

Located In An Island/Median?

Data



N/A B 1 Tone Audible Range?

Possible Solutions: Remove & Replace Crossing Striping. Provide Push Button Extension. Remove and Replace Clear Space.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R209.1, R404.2, R404.3, R406.2

Total Cost:

No N/A B 2 Tone Audible Range?

1400.00 N/A B 1 FWD Approach Constrained?





					N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
					N/A	B 1 PARA Approach Constraine	ed? No	N/A	B 2 PARA Approach Constrained?	N/A
				Yes	B 1 PARA Approach Reach (in)	7.0	N/A	B 2 PARA Approach Reach (in)	N/A	
						B 1 PARA Approach Width (in)	48.0	N/A	B 2 PARA Approach Width (in)	N/A
					N/A	B 1 PARA Approach Obstruction	on? Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance					N/A	B 1 PARA Approach Obstruction	on Dist (in) 5.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No	B 1 Clear Floor Space Slope (%) 3.0	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A	B 1 VibroTact Arrow?	No	N/A B 2 VibroTact Arrow?	N/A	No	B 1 Clear Floor Space XSlope	(%) 4.7	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A	B 1 VibroTact Parallel to Xing?	No	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A	B 1 PAR Slope (%)	1.5	N/A	B 2 PAR Slope (%)	N/A
N/A	B 1 VibroTact Contrast	No	N/A B 2 VibroTact Contrast	N/A	Yes	B 1 Height (in)	45.0	N/A	B 2 Height (in)	N/A
N/A	B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	Yes	B 1 Pressure (#)	1.5	N/A	B 2 Pressure (#)	N/A
N/A	B 1 Pilot Light Illumination?	No	N/A B 2 Pilot Light Illumination?	N/A	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A	B 1 Verbal Walk Cycle?	No	N/A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance					
N/A	B 1 Verbal Message Audible?	No	N/A B 2 Verbal Message Audible?	N/A	No	B 1 Clear Xing Direction? No.	otClearlyMarked	N/A	B 2 Clear Xing Direction?	N/A
N/A	B 1 Locator Tone?	No	N/A B 2 Locator Tone?	N/A		B 1 Crossing Direction	To E		B 2 Crossing Direction	N/A
N/A	B 1 Percussive Walk Cycle?	No	N/A B 2 Percussive Walk Cycle?	N/A	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A
N/A	B 1 Extended Press Feature?	No	N/A B 2 Extended Press Feature?	N/A	Yes	B 1 DistanceTo Curb (in)	49.0	N/A	B 2 DistanceTo Curb (in)	N/A

N/A

Yes B 1 Diameter (in)