cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



| Intersection ID: N/A | Main Street: | | ross Street: N/A | oss Street: N/A | | | Location: N/A | | |
|--|---|--|----------------------------|------------------------------------|----------------------------|---------------------|--------------------------|-----------------|--------------------|
| ADA ID: 7DEC0B224A60 | Signal Type:O | ne Push Button-Non APS | Overall Co | ompliance: No | Severity Score: | BTN 1:N/ | A BTN 2: N/A | No BTN: | N/A |
| Codes | Field Measurements/Component Compliance | | | | | | | | |
| | | | | | | | pliance Description Data | | |
| | AND AND | Possible Solutions: Replace Sign Button With APS Button on New I Remove & Relocate Sign. | | Button Count | В | | Distant to Additional | | 269.0 |
| | a balan | | | Additional Buttor | | Yes | Additional Button ID | | 4A5A7E41 |
| 1 2 2 1 1 2 | The street | | | N/A Signal Buttons Required? | | N/A N/A | Additional Ped Post | | N/A |
| | CT AND | | | How Many Ped Street Xings? | | 1 | Located In An Island | | No |
| | | Surveyor Notes: N/A | | N/A B 1 Sign Present? | | Yes N/A | B 2 Sign Present? | | N/A |
| | | - | | Yes B 1 Sign Purpos | | | B 2 Sign Purpose? | | N/A |
| | 11 | PROW/ADA: TMUTCD 4e.08, R404.2, R406.2 | | Yes B 1 Sign Lettering & Contrast? | | Yes N/A | B 2 Sign Lettering & | Contrast? | N/A |
| | and the | | | Yes B 1 Parallel To XWalk? | | Yes N/A | B 2 Parallel To XWa | lk? | N/A |
| CONTROL BOOM | A PARTY | | | Yes B 1 PAR to Button? | | Yes N/A | B 2 PAR to Button? | | N/A |
| BUDDON | | | Yes B 1 PAR to XWalk? | | Yes N/A | B 2 PAR to XWalk? | | N/A | |
| The | | | Yes B 1 Clear Floor Space? | | Yes N/A | B 2 Clear Floor Spa | ce? | N/A | |
| | 13 WILL | | | N/A B 1 FWD Approa | ach? | Yes N/A | B 2 FWD Approach? | ? | N/A |
| | K L a | Total Cost: \$ | 650.00 | N/A B 1 FWD Approa | ach Constrained? | No N/A | B 2 FWD Approach | Constrained? | N/A |
| | | | | No B 1 FWD Approa | ach Reach (in) | 10.0 N/A | B 2 FWD Approach | Reach (in) | N/A |
| | | | | N/A B 1 FWD Approa | ach Width (in) | N/A N/A | B 2 FWD Approach | Width (in) | N/A |
| | | | a mana | N/A B 1 FWD Approa | ach Obstruction? | Yes N/A | B 2 FWD Approach | Obstruction? | N/A |
| | | | | N/A B 1 FWD Approa | ach Obstruction Dist (in) | 3.0 N/A | B 2 FWD Approach | ObstructionDist | t (in) N/A |
| | | | | N/A B 1 PARA Appro | ach? | Yes N/A | B 2 PARA Approach | ? | N/A |
| | | | | N/A B 1 PARA Approach Constrained? | | No N/A | B 2 PARA Approach | Constrained? | N/A |
| | | | | Yes B 1 PARA Approach Reach (in) | | 6.0 N/A | B 2 PARA Approach | Reach (in) | N/A |
| | | | | N/A B 1 PARA Approach Width (in) | | N/A N/A | B 2 PARA Approach | Width (in) | N/A |
| | | N/A B 1 PARA Appro | each Obstruction? | Yes N/A | B 2 PARA Approach | Obstruction? | N/A | | |
| APS Compliance | | | | N/A B 1 PARA Appro | each Obstruction Dist (in) | 3.0 N/A | B 2 PARA Approach | ObstructionDis | st (in) N/A |
| Is Button 1 APS or Non-APS? | NonAPS | Is Button 2 APS or Non-APS? | N/A | Yes B 1 Clear Floor S | Space Slope (%) | 4.8 N/A | B 2 Clear Floor Spa | ce Slope (%) | N/A |
| N/A B 1 VibroTact Arrow? | N/A N/A | B 2 VibroTact Arrow? | N/A | No B 1 Clear Floor S | Space XSlope (%) | 3.4 N/A | B 2 Clear Floor Spa | ce XSlope (%) | N/A |
| N/A B 1 VibroTact Parallel to Xing? | N/A N/A | B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope (| (%) | 6.1 N/A | B 2 PAR Slope (%) | | N/A |
| N/A B 1 VibroTact Contrast | N/A N/A | B 2 VibroTact Contrast | N/A | Yes B 1 Height (in) | | 43.0 N/A | B 2 Height (in) | | N/A |
| N/A B1 Pilot Light? | | B 2 Pilot Light? | N/A | Yes B 1 Pressure (#) | | 2.0 N/A | B 2 Pressure (#) | | N/A |
| N/A B 1 Pilot Light Illumination? | N/A N/A | B 2 Pilot Light Illumination? | N/A | Yes B 1 Closed Fist (| | • | B 2 Closed Fist Ope | eration? | N/A |
| N/A B 1 Verbal Walk Cycle? | N/A N/A | N/A N/A B 2 Verbal Walk Cycle? N/A | | MUTCD Co | | | | | |
| N/A B 1 Verbal Message Audible? | | B 2 Verbal Message Audible? | N/A | Yes B 1 Clear Xing D | - | | B 2 Clear Xing Direc | | N/A |
| N/A B 1 Locator Tone? | | B 2 Locator Tone? | N/A | B 1 Crossing Dir | | To NE | B 2 Crossing Directi | | N/A |
| N/A B 1 Percussive Walk Cycle? | | B 2 Percussive Walk Cycle? | N/A | Yes B 1 DistanceTo > | | | B 2 DistanceTo XWa | | N/A |
| N/A B 1 Extended Press Feature? | | B 2 Extended Press Feature? | N/A | No B 1 DistanceTo (| | | B 2 DistanceTo Curb | o (in) | N/A |
| N/A B 1 Tone Audible Range? | N/A N/A | B 2 Tone Audible Range? | N/A | Yes B 1 Diameter (in |) | 2.0 N/A | B 2 Diameter (in) | | N/A |