

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A N/A No

N/A N/A N/A

N/A N/A N/A

N/A N/A N/A N/A

> N/A N/A N/A

> N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 8090D5CB05B6 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data

Compliance Description

2.0 N/A B 2 Diameter (in)



N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R406.2

Total Cost:

N/A N/A B 2 Tone Audible Range?

650.00



		Button Count	Button1	N/A	Distant to Additional Button (in)
		Additional Button Present?	No		Additional Button ID
	N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required
		How Many Ped Street Xings?	2		Located In An Island/Median?
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?
)	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?
	No	B 1 FWD Approach Reach (in)	1.0	N/A	B 2 FWD Approach Reach (in)
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?
	N/A	B 1 FWD Approach Obstruction Dist (i	n) 9.0	N/A	B 2 FWD Approach ObstructionDist (in)
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?
	Yes	B 1 PARA Approach Reach (in)	1.0	N/A	B 2 PARA Approach Reach (in)
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?



N/A N/A N/A B 1 PARA Approach Obstruction? **Yes N/A** B 2 PARA Approach Obstruction? N/A B 1 PARA Approach Obstruction Dist (in) APS Compliance 9.0 N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 1 APS or Non-APS? NonAPS Is Button 2 APS or Non-APS? Yes B 1 Clear Floor Space Slope (%) N/A 7.3 N/A B 2 Clear Floor Space Slope (%) N/A N/A N/A B 2 VibroTact Arrow? N/A Yes B 1 Clear Floor Space XSlope (%) 2.0 N/A B 2 Clear Floor Space XSlope (%) N/A N/A B 1 VibroTact Arrow? N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) 7.6 N/A B 2 PAR Slope (%) N/A N/A 42.0 N/A B 2 Height (in) N/A N/A B 1 VibroTact Contrast N/A N/A B 2 VibroTact Contrast Yes B 1 Height (in) N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? Yes B 1 Pressure (#) N/A 2.0 N/A B 2 Pressure (#) N/A **N/A** B 2 Pilot Light Illumination? Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A **N/A** B 1 Pilot Light Illumination? N/A N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** ClearlyMarked N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A N/A B 2 Verbal Message Audible? N/A Yes B 1 Clear Xing Direction? N/A N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A **B 1 Crossing Direction** To SE **B 2 Crossing Direction** N/A N/A N/A B 1 Percussive Walk Cycle? N/A B 2 Percussive Walk Cycle? N/A Yes B 1 DistanceTo XWalk (in) 0.0 N/A B 2 DistanceTo XWalk (in) N/A N/A B 2 Extended Press Feature? N/A 87.0 N/A B 2 DistanceTo Curb (in) N/A N/A B 1 Extended Press Feature? No B 1 DistanceTo Curb (in)

N/A

Yes B 1 Diameter (in)